



Eidgenössische Kommission für Strahlenschutz  
Commission fédérale de radioprotection  
Commissione federale della radioprotezione  
Federal Commission on radiation protection

## Workshop 2016

*Démantèlement : stratégie et enjeux de radioprotection*  
*Rückbau : Strategie und Strahlenschutzherausforderungen*  
*Dismantling : Strategy and Radiation Protection challenges*



Sicht auf BAG Gebäude vom Liebefeld Parksee, Foto Thomas Steffel

Bern, April 15 2016



**Eröffnungsworte zum KSR-Seminar Rückbau: Strategie und Strahlenschutzherausforderungen**  
**P. Strupler, Direktor vom Bundesamt für Gesundheit**

Es freut mich, dass die Eidgenössische Kommission für Strahlenschutz den Rückbau von Kernanlagen zum Thema ihres diesjährigen Seminars gemacht hat, und ehrt mich, dass ich diese Tagung eröffnen darf. Unabhängig von den Kontroversen über die Kernenergie ist der Rückbau von Kernanlagen für uns alle von grosser Bedeutung. Eine wichtige Epoche der Technikgeschichte muss abgeschlossen werden, und dies muss wissenschaftlich fundiert, transparent, ohne negative Haltung, ohne Parteilichkeit und ohne Nostalgie geschehen. In den kommenden Jahrzehnten wird der Rückbau von Kernanlagen für den Strahlenschutz in der Schweiz eine immer wiederkehrende Problematik darstellen.

Unser Amt ist für den Schutz der Bevölkerung und der Umwelt vor den Gefahren der ionisierenden Strahlung zuständig und wird daher beim Rückbauprozess ein wichtiger Partner sein. Es ist sehr zu begrüssen, dass die Kommission die Diskussion über die Probleme und die Herausforderungen des Rückbaus bereits heute lanciert. Die Schutzanforderungen sind beim Rückbau sehr vielschichtig: Es geht um den Schutz der Arbeitenden, die Abfallbewirtschaftung, den Schutz der Bevölkerung, den Schutz der Umwelt und die Standortsanierung. Dabei ergeben sich Probleme, die sowohl in technischer als auch in gesellschaftlicher Hinsicht neue Dimensionen erreichen. Eine konsequente, sozial verträgliche, nachhaltige Herangehensweise wird erforderlich sein, damit wir den künftigen Generationen eine saubere und klar dokumentierte Situation hinterlassen können. Dies setzt grosse Transparenz voraus, und das heutige Seminar zielt in diese Richtung.

Die Aufsicht über den Rückbau gehört zu den Aufgaben des ENSI, und wie Ihnen der erste Referent darlegen wird, hat sich das ENSI bereits eingehend mit diesem Thema beschäftigt. Doch angesichts der zahlreichen Aspekte, die in diesem Zusammenhang berücksichtigt werden müssen, wird dieses Vorhaben etliche Ämter und Dienststellen auf nationaler, kantonaler und kommunaler Ebene betreffen. Daher braucht es für dessen Erfolg eine gemeinsame Strategie und ein koordiniertes Vorgehen. In diesem Sinn bildet das heutige Seminar den ersten Schritt auf einem langen Weg, den wir in den kommenden Jahren gemeinsam zu gehen haben. Auch die Zusammenarbeit mit anderen Ländern wie Deutschland und Frankreich ist im Bereich des Rückbaus äusserst wichtig.

Ich danke den Referentinnen und Referenten an dieser Stelle herzlich für die Grundlagen, mit denen sie unsere Betrachtungen untermauern. Ich danke Ihnen allen für Ihr Interesse und für Ihr Engagement in dieser Sache. Ihr Beitrag ist wichtig, denn es handelt sich um ein gesamtschweizerisches Unterfangen, das auf einem breiten Konsens beruhen muss. Ich wünsche Ihnen allen ein interessantes und fruchtbare Seminar.

### **Mot d'ouverture pour l'atelier de la CPR sur le démantèlement des centrales nucléaires**

Je suis heureux que la Commission fédérale de radioprotection ait choisi comme thème de son atelier 2016 le démantèlement des centrales nucléaires et qu'il me soit donné la possibilité d'ouvrir cette réunion. Au-delà des controverses sur l'énergie nucléaire, la démarche de démantèlement revêt une grande importance pour nous tous. Il s'agit de terminer un épisode important de l'histoire de la technique et de le faire de la manière la plus scientifique et la plus transparente possible, sans attitude négative, sans esprit partisan et sans nostalgie. Le démantèlement va être au cours de ces prochaines décennies un thème récurrent pour la radioprotection en Suisse.

Notre office, en charge de la protection de la population et de l'environnement contre les dangers de la radiation ionisante sera un partenaire incontournable de la démarche. Ainsi je salue la volonté de la Commission d'ouvrir la discussion dès aujourd'hui sur les problèmes nouveaux et les défis que le démantèlement soulève. Les enjeux de protection dans le cadre du démantèlement sont multiples : protection des travailleurs, gestion des déchets, protection de la population, protection de l'environnement, réhabilitation du site. Les problèmes qui seront rencontrés présentent des aspects nouveaux, aussi bien au niveau technique que social, et exigeront une approche rigoureuse et socialement respectueuse qui s'inscrive dans le long terme afin de léguer une situation propre et documentée aux générations futures. Ceci exige une grande transparence et l'atelier de ce jour œuvre dans cette direction.



La surveillance du démantèlement fait partie des missions de l'IFSN/ENSI et, comme vous en fera part notre premier conférencier, une réflexion avancée a été menée au sein de cet organisme. Toutefois, vu la diversité des pratiques qui devront être mises à contribution, la démarche concerne de nombreux offices et services, au niveau fédéral, cantonal et communal. Ainsi une mise en commun de la stratégie et une coordination des activités seront nécessaires au succès du projet. Dans ce sens l'atelier de ce jour constitue le premier pas sur un long chemin que nous aurons à parcourir ensemble dans les prochaines années. La collaboration avec d'autres pays, comme l'Allemagne et la France par exemple, est également d'une importance majeure dans le domaine du démantèlement.

Je remercie d'ores et déjà et chaleureusement les conférenciers qui apporteront les matériaux de base à notre réflexion. Je vous remercie tous pour votre intérêt et votre participation à cette réflexion. Votre contribution est importante car il s'agit d'une entreprise nationale qui doit reposer sur un large consensus. Je vous souhaite à tous une journée intéressante et fructueuse.



## Decommissioning: What should we do and what are the strategies?

<p><b>Swiss Federal Nuclear Safety Inspectorate ENSI</b></p> <p><b>Decommissioning of Nuclear Installations in Switzerland: Experiences and New Challenges</b></p> <p>Radiation Protection Workshop on Dismantling Strategy and Radiation Protection Challenges Federal Commission on Radiation Protection, Liebefeld, April 8, 2016</p> <p>Torsten Kretsch Swiss Federal Nuclear Safety Inspectorate ENSI</p>	<p><b>Definition of Decommissioning</b></p> <p>Decommissioning of a nuclear installation includes all necessary activities for the installation and/or the site to be used for other purposes, no longer presents a radiological hazard, and is thus no longer subject to nuclear energy legislation.</p> <p>(Message to the Nuclear Energy Act of Switzerland)</p>																								
<p><b>Experience in Switzerland</b></p> <table border="1"> <thead> <tr> <th>Installation</th> <th>Operation time</th> <th>Decommissioning</th> </tr> </thead> <tbody> <tr> <td>VAKL Lucens</td> <td>1968-1969</td> <td>Decommissioned 1995/2004</td> </tr> <tr> <td>PSI RR DIORIT</td> <td>1960-1977</td> <td>End of nuclear dismantling activities</td> </tr> <tr> <td>Uni Genève RR</td> <td>1958-1987</td> <td>Decommissioned 1989</td> </tr> <tr> <td>PSI RR SAPHIR</td> <td>1957-1994</td> <td>End of nuclear dismantling activities</td> </tr> <tr> <td>PSI VVA</td> <td>1974-2002</td> <td>Decommissioning phase 1</td> </tr> <tr> <td>PSI RR PROTEUS</td> <td>1968-2011</td> <td>Decommissioning order expected</td> </tr> <tr> <td>Uni Basel RR</td> <td>1960-2015</td> <td>Decommissioning project expected</td> </tr> </tbody> </table>	Installation	Operation time	Decommissioning	VAKL Lucens	1968-1969	Decommissioned 1995/2004	PSI RR DIORIT	1960-1977	End of nuclear dismantling activities	Uni Genève RR	1958-1987	Decommissioned 1989	PSI RR SAPHIR	1957-1994	End of nuclear dismantling activities	PSI VVA	1974-2002	Decommissioning phase 1	PSI RR PROTEUS	1968-2011	Decommissioning order expected	Uni Basel RR	1960-2015	Decommissioning project expected	<p><b>Current Projects</b></p> <p><b>Pilot Incineration Plant at PSI</b></p> <ul style="list-style-type: none"> <li>Incineration of low active waste at 1200 °C</li> <li>Decommissioning project is granted</li> <li>Preparatory work for decommissioning completed (restricted access area, ventilation system, operating regulations)</li> <li>Start dismantling phase 1: March 2016</li> </ul>
Installation	Operation time	Decommissioning																							
VAKL Lucens	1968-1969	Decommissioned 1995/2004																							
PSI RR DIORIT	1960-1977	End of nuclear dismantling activities																							
Uni Genève RR	1958-1987	Decommissioned 1989																							
PSI RR SAPHIR	1957-1994	End of nuclear dismantling activities																							
PSI VVA	1974-2002	Decommissioning phase 1																							
PSI RR PROTEUS	1968-2011	Decommissioning order expected																							
Uni Basel RR	1960-2015	Decommissioning project expected																							
<p><b>Current Projects</b></p> <p><b>Basel University</b></p> <p><b>Research Reactor AGN-211-P</b></p> <ul style="list-style-type: none"> <li>Complete core (highly enriched Uranium) transported to the U.S.</li> <li>Decommissioning project in preparation</li> </ul>	<p><b>Nuclear Power Plants in Switzerland</b></p> <table border="1"> <thead> <tr> <th>NPP</th> <th>Type</th> <th>MW<sub>e</sub></th> <th>Manufacturer</th> </tr> </thead> <tbody> <tr> <td>Beznau I</td> <td>PWR</td> <td>365</td> <td>Westinghouse</td> </tr> <tr> <td>Beznau II</td> <td>PWR</td> <td>365</td> <td>Westinghouse</td> </tr> <tr> <td>Mühleberg</td> <td>BWR</td> <td>373</td> <td>General Electric</td> </tr> <tr> <td>Gösgen</td> <td>PWR</td> <td>1010</td> <td>Siemens-KWU</td> </tr> <tr> <td>Leibstadt</td> <td>BWR</td> <td>1220</td> <td>General Electric</td> </tr> </tbody> </table>	NPP	Type	MW <sub>e</sub>	Manufacturer	Beznau I	PWR	365	Westinghouse	Beznau II	PWR	365	Westinghouse	Mühleberg	BWR	373	General Electric	Gösgen	PWR	1010	Siemens-KWU	Leibstadt	BWR	1220	General Electric
NPP	Type	MW <sub>e</sub>	Manufacturer																						
Beznau I	PWR	365	Westinghouse																						
Beznau II	PWR	365	Westinghouse																						
Mühleberg	BWR	373	General Electric																						
Gösgen	PWR	1010	Siemens-KWU																						
Leibstadt	BWR	1220	General Electric																						
<p><b>Legal Framework: Nuclear Energy Act</b></p> <p>Gradual detailing and specification Legal requirement to update the decommissioning plan</p> <pre> graph LR     A[Decommissioning CONCEPT] --&gt; B[Decommissioning PLAN]     B --&gt; C[Decommissioning PROJECT]     C --&gt; D[Decommissioning PROJECT]     style C fill:#0070C0,color:#fff     style D fill:#0070C0,color:#fff     C --&gt; D     C --&gt; E[NEA Art. 16 ... for construction licence application]     C --&gt; F[NEA Art. 27 ... for decommissioning order application]     </pre>	<p><b>Legal Framework (Decommissioning Plans)</b></p>																								



<p><b>Legal Framework (NEA, NEO, ENSI-G17)</b></p> <p><b>Decommissioning obligation (owner)</b></p> <p><b>Decommissioning project (owner)</b></p> <ul style="list-style-type: none"> <li>Includes a phase concept specified by the owner</li> <li>Is assessed and supervised by ENSI</li> </ul> <p><b>Decommissioning order (DETEC)</b></p> <ul style="list-style-type: none"> <li>Replaces the operating license</li> <li>May be legally binding at the time of final shutdown</li> <li>Regulates ENSI's requirements and approvals (phases and working steps)</li> <li>Based on the decommissioning project of the owner</li> </ul> <p><b>Release from NEA (DETEC)</b></p>	<p><b>Legal Framework (NEO)</b></p> <p><b>Content of the Decommissioning Project:</b></p> <ul style="list-style-type: none"> <li>Concept of different phases</li> <li>Each step in the process of dismantling and demolition</li> <li>Procedure for separating radioactive from non-radioactive waste and management of the radioactive waste</li> <li>Measures to protect personnel against radiation and to prevent the release of radioactive substances into the environment</li> <li>Security measures</li> <li>Accident analysis and emergency preparedness measures</li> <li>Personnel and organisation</li> <li>Quality management program</li> <li>Environmental impact report</li> <li>Summary of costs and securing the necessary financing</li> </ul>
<p>Torsten Kretsch: Decommissioning of Nuclear Installations in Switzerland: Experiences and new Challenges Decommissioning Strategy and Radiation Protection Challenges, Workshop Federal Commission on Radiation Protection, Liebefeld, April 8, 2016</p> <p>9</p> <p><b>Legal Framework</b></p> <p>Phase concept according to radiological hazards (PWR schematic)</p> <p>11</p>	<p>Torsten Kretsch: Decommissioning of Nuclear Installations in Switzerland: Experiences and new Challenges Decommissioning Strategy and Radiation Protection Challenges, Workshop Federal Commission on Radiation Protection, Liebefeld, April 8, 2016</p> <p>10</p> <p><b>Legal Framework (NEO)</b></p> <p>The decommissioning order specifies the following details:</p> <ul style="list-style-type: none"> <li>Scope of decommissioning activities</li> <li>The various decommissioning phases, in particular the duration of any safe enclosure of the nuclear installation</li> <li>Limits for the discharge of radioactive substances into the environment</li> <li>Monitoring of immissions of radioactive substances and of direct radiation</li> <li>Organisation</li> </ul>
<p>Torsten Kretsch: Decommissioning of Nuclear Installations in Switzerland: Experiences and new Challenges Decommissioning Strategy and Radiation Protection Challenges, Workshop Federal Commission on Radiation Protection, Liebefeld, April 8, 2016</p> <p>12</p> <p><b>Legal Framework (NEO)</b></p> <p>The decommissioning order defines the need for an approval especially for the following activities:</p> <ul style="list-style-type: none"> <li>Procedure for the clearance measurement of resulting materials</li> <li>Conditioning of resulting radioactive waste</li> <li>Demolition of buildings after their decontamination and clearance measurement</li> <li>Non-nuclear use of installations after completion of the decommissioning process</li> <li>Repeal of security measures</li> <li>In the case of decommissioning of nuclear power plants, disassembly of the reactor vessel and its surrounding building elements</li> </ul>	<p>Torsten Kretsch: Decommissioning of Nuclear Installations in Switzerland: Experiences and new Challenges Decommissioning Strategy and Radiation Protection Challenges, Workshop Federal Commission on Radiation Protection, Liebefeld, April 8, 2016</p> <p>13</p> <p><b>Legal Framework (ENSI-G17)</b></p> <p>The Guideline ENSI-G17: <i>Decommissioning of nuclear installations</i></p> <p>Requirements for decommissioning:</p> <ul style="list-style-type: none"> <li>Specifies the requirements from NEO</li> </ul> <p>Requirements for the application documents:</p> <ul style="list-style-type: none"> <li>Decommissioning project</li> <li>Post-shutdown period</li> <li>Decommissioning phases (safety analysis report)</li> <li>Final report</li> </ul> <p>14</p>
<p>Torsten Kretsch: Decommissioning of Nuclear Installations in Switzerland: Experiences and new Challenges Decommissioning Strategy and Radiation Protection Challenges, Workshop Federal Commission on Radiation Protection, Liebefeld, April 8, 2016</p> <p>15</p> <p><b>Legal Framework (ENSI-G17)</b></p> <p>Important aspects:</p> <ul style="list-style-type: none"> <li>Subdivision into phases by owners</li> <li>Approval for phases and working steps by ENSI</li> <li>Removal of nuclear fuel as soon as possible to another nuclear installation (no binding to post-shutdown operation)</li> <li>Decommissioning is possible with nuclear fuel on site</li> <li>Safe enclosure is considered as a phase of the decommissioning project</li> </ul>	<p><b>Legal Framework</b></p> <p>With a planned shutdown the classic post-shutdown phase can be completely avoided or kept short!</p> <p>This requires that:</p> <ul style="list-style-type: none"> <li>the decommissioning project is ready and submitted at a very early stage of the decommissioning process,</li> <li>the decommission order becomes legally binding simultaneously with the final shutdown.</li> </ul> <p>→ Transition from classical to technical post-shutdown operation</p> <p>16</p>





## Decommissioning of nuclear facilities – technical issues and conventional waste treatment

<p><b>KIT</b> Karlsruher Institut für Technologie</p> <p><b>Rückbau kerntechnischer Anlagen - Offene technische Fragen und der Umgang mit konventionellen Abfällen</b></p> <p>Prof. Dr.-Ing. Sascha Gentes Dipl.-Ing. Hedjeh Emami-Far</p> <p>Rückbau kontaminierte und kerntechnische Bauwerke - Prof. Dr.-Ing. Sascha Gentes</p> <p>KIT – Die Forschungsuniversität der Helmholtz-Gemeinschaft www.kit.edu</p>	<p><b>Institut für Technologie und Management im Baubetrieb (TMB)</b></p> <p>Rückbau ist eine von drei Säulen am TMB. Das Institut vertritt die komplette Vertiefungsrichtung <b>BAUBETRIEB</b> innerhalb der Fakultät für Bauingenieur-, Geo- und Umweltwissenschaften am KIT.</p> <p><b>Aktuelle Zahlen</b></p> <ul style="list-style-type: none"> <li>ca. 45 Vertieferstudenten pro Jahr</li> <li>40 Beschäftigte, davon</li> <li>3 Professoren</li> <li>30 wissenschaftliche Mitarbeiter</li> <li>5 Werkstattmitarbeiter</li> </ul> <p><b>TMB</b></p> <p>Rückbau kontaminierte und kerntechnische Bauwerke www.kit.edu</p>
<p><b>Forschungsthemen kerntechnischer Rückbau</b></p> <ul style="list-style-type: none"> <li>Standardisierter Rückbau von KKW</li> <li>Technologien und Verfahren</li> <li>„Management“             <ul style="list-style-type: none"> <li>Verringerung der Sekundärabfälle</li> <li>Automation und Fernhandhabung der Verfahren</li> <li>Leistungsoptimierung bestehender Verfahren</li> <li>Neuentwicklung von Technologien</li> </ul> </li> </ul> <p>→ Stahl, Edelstahl und Stahlbeton → Rückholtechnologien für Endlager</p> <p>3 09.04.2016 Prof. Dr.-Ing. Sascha Gentes Rückbau kontaminierte und kerntechnische Bauwerke</p>	<p><b>Anwendung in der Praxis</b></p> <p>4 09.04.2016 Prof. Dr.-Ing. Sascha Gentes Rückbau kontaminierte und kerntechnische Bauwerke</p>
<p><b>Optimierung der verfahrenstechnischen Kette „Abtrag kontaminiert Oberflächen“ - AKOF</b></p> <p><b>Forschungsschwerpunkte und -ziele</b></p> <ul style="list-style-type: none"> <li>Weiterentwicklung und Optimierung einer Bodenfräse für einen Oberflächenabtrag von 10 mm Beton in einem Arbeitsgang</li> <li>Konstruktion eines geeigneten Manipulators</li> </ul> <p><b>Projektpartner</b></p> <ul style="list-style-type: none"> <li>Energie Baden-Württemberg AG (EnBW)</li> </ul> <p>→ EnBW</p> <p>5 09.04.2016 Prof. Dr.-Ing. Sascha Gentes Rückbau kontaminierte und kerntechnische Bauwerke</p>	<p><b>Forschungsmethodik: praktische Versuche</b></p> <ul style="list-style-type: none"> <li>Aufbau eines Versuchsstandes</li> <li>Installation von Messtechnik (Kraftsensoren)</li> </ul> <p>6 09.04.2016 Prof. Dr.-Ing. Sascha Gentes Rückbau kontaminierte und kerntechnische Bauwerke</p>
<p><b>Forschungsmethodik: Verschleiß</b></p> <ul style="list-style-type: none"> <li>Reib- und Prallverschleiß an den Hartmetallspitzen und den Lamellenflanken</li> <li>Messung des fortschreitenden Materialverlustes</li> </ul> <p>Laufzeit: 0 m Zustelltiefe: 3 mm Drehzahl: 30 Hz</p> <p>Laufzeit: 540 m Zustelltiefe: 3 mm Drehzahl: 30 Hz</p> <p>7 09.04.2016 Prof. Dr.-Ing. Sascha Gentes Rückbau kontaminierte und kerntechnische Bauwerke</p>	<p><b>Optimierungsergebnisse und Einsatzvorteile</b></p> <ul style="list-style-type: none"> <li>Anordnung der HM-Spitzen an den Flanken → Höhere Standzeit</li> <li>Verstärkung der Lamelle durch HM-Ringe → Höhere Abtragsleistung</li> </ul> <p>→ Sekundärabfall minimiert</p> <p>8 09.04.2016 Prof. Dr.-Ing. Sascha Gentes Rückbau kontaminierte und kerntechnische Bauwerke</p>





### Rückholtechnologien Endlager

**Technikumsversuche**

- Lösetechnologien von Gebinden aus einer verfestigten Salzmatrix
- Simulation der Krafteinleitung auf das umgebende Gebirge

17 09.04.2016 Prof. Dr.-Ing. Sascha Gentes  
Rückbau konventioneller und kerntechnischer Bauwerke

### Kooperation mit der IAEA

**Forschungsschwerpunkte und -ziele**

- Mitarbeiter im „Research Reactor Decommissioning Project“
- Schulungen im Bereich Technologie und Management des Rückbaus kerntechnischer Anlagen für internationale Fachgruppen
- Mitglied im Advisory Board des International Decommissioning Network (IDN) der IAEA

18 09.04.2016 Prof. Dr.-Ing. Sascha Gentes  
Rückbau konventioneller und kerntechnischer Bauwerke

### Kooperationspartner

■ AREVA	
■ Bundesamt für Strahlenschutz (Asse)	
■ EnBW Kernkraft GmbH	
■ E.ON Kernkraft	
■ Herrenknecht AG	
■ Hilti Corporation	
■ IAEA	
■ Kraftanlagen Heidelberg	
■ NUKEM GmbH	
■ Sat. Kerntechnik GmbH	
■ Siempelkamp Nukleartechnik GmbH	
■ TU Dresden, Institute am KIT	
■ Wiederaufarbeitungsanlage Karlsruhe (WAK)	

19 09.04.2016 Prof. Dr.-Ing. Sascha Gentes  
Rückbau konventioneller und kerntechnischer Bauwerke

### Direkte Projektmitarbeit – Kalterprobung

**Direkte Projektmitarbeit – Kalterprobung**

20 09.04.2016 Prof. Dr.-Ing. Sascha Gentes  
Rückbau konventioneller und kerntechnischer Bauwerke

### Direkte Projektmitarbeit – Kalterprobung

**Betonzerkleinerung und Befülleinrichtung**

21 09.04.2016 Prof. Dr.-Ing. Sascha Gentes  
Rückbau konventioneller und kerntechnischer Bauwerke

### Möglichkeiten der Universität in der Lehre

**„Rückbau kerntechnischer Anlagen“**

- Einrichtung des Moduls
- Aufbau und Betrieb eines KKW
- Strahlung, Strahlenschutz und Messtechnik
- Genehmigungsplanung
- Dekontamination, Oberflächenbehandlung und Fernentfernungstechniken
- Abbruch- und Demontagetechniken
- Trennen von Stahl und Stahlbeton
- Management des gesamten Rückbaus
- Exkursionen zu aktuellen Rückbaustandorten

22 09.04.2016 Prof. Dr.-Ing. Sascha Gentes  
Rückbau konventioneller und kerntechnischer Bauwerke

### Aktuelles Vorlesungssemester: 20 Studenten

**Forschungsthemen konventioneller Rückbau**

23 09.04.2016 Prof. Dr.-Ing. Sascha Gentes  
Rückbau konventioneller und kerntechnischer Bauwerke

24 09.04.2016 Prof. Dr.-Ing. Sascha Gentes  
Rückbau konventioneller und kerntechnischer Bauwerke

### Detailausschnitt A5

- Ausbau
- u.a. Karlsruhe nach Offenburg



25 09.04.2016 Prof. Dr.-Ing. Sascha Gentes

**KIT**  
Karlsruhe Institute of Technology

### Straßenbau - Asphalt

- Aus Sicht des Bauingenieurs....




**KIT**  
Karlsruhe Institute of Technology

26 09.04.2016 Prof. Dr.-Ing. Sascha Gentes

Rückbau konventioneller und keramischer Bauwerke

### Straßenbau - Asphalt

- Aus Sicht des Entsorgers
- Baden-Württemberg:
- PAK: gefährlich ab 200 mg/ kg
- Landkreise und die Andienpflicht
- Lagerung und das BlmSchG
- Baufeld im Wasserschutzgebiet
- Lagerung außerhalb Baufeld



27 09.04.2016 Prof. Dr.-Ing. Sascha Gentes

**KIT**  
Karlsruhe Institute of Technology

### Beispiel gefährliche / nichtgefährliche Abfälle

17 05 04: Boden und Steine mit Ausnahme derjenigen, die unter 17 05 03 fallen

17 05 03\*: Boden und Steine, die gefährliche Stoffe enthalten



#### Beispiel: PAK-belasteter Boden

Rheinland-Pfalz: gefährlich ab 30 mg/ kg PAK

Baden-Württemberg: gefährlich ab 200 mg/ kg PAK

Hessen: gefährlich ab 400 mg/ kg PAK

Bayern: gefährlich ab 1.000 mg / kg PAK

28 09.04.2016 Prof. Dr.-Ing. Sascha Gentes

Rückbau konventioneller und keramischer Bauwerke

### Möglichkeiten der Universität in der Lehre

- Einrichtung des Moduls

#### „Umwelt- und recyclinggerechte Demontage von Bauwerken“

- Stand der Wissenschaft und Technik
- Prozesskette: Maschineller Abbruch, Transport, Aufbereitung, Deponierung und Entsorgung
- Abbruchantrag bis Maschineneinsatzplanung
- Arbeits- und Immissionsschutz
- Umgang mit Schadstoffen
- VDI- und Deponierrichtlinien
- Kalkulation mittels Praxisbeispiel
- Exkursionen



29 09.04.2016 Prof. Dr.-Ing. Sascha Gentes

Rückbau konventioneller und keramischer Bauwerke

Haben Sie Fragen?

**KIT**  
Karlsruhe Institute of Technology

30 09.04.2016 Prof. Dr.-Ing. Sascha Gentes

Rückbau konventioneller und keramischer Bauwerke



## Knowing that and knowing how - Concerning motivational aspects of safety-related knowledge management to decommissioning

<p><b>n w</b> Fachhochschule Nordwestschweiz Hochschule für Angewandte Psychologie</p> <p>Radiation Protection Workshop Federal Commission on Radiation Protection Bern, 8. April 2016</p> <p><b>Knowing That and Knowing How:</b></p> <p><b>Motivationale Aspekte sicherheitsbezogenen Wissensmanagements bei Nachbetrieb und Rückbau</b></p> <p>Prof. Dr. Frank Ritz Institut Mensch in komplexen Systemen</p>	<p><b>n w</b> Fachhochschule Nordwestschweiz Hochschule für Angewandte Psychologie</p> <p><b>Inhalt</b></p> <ol style="list-style-type: none"> <li>1. Vorbemerkung</li> <li>2. Strategische Ausgangslage und motivationale Herausforderungen</li> <li>3. Rückbau als Pionieraufgabe</li> <li>4. Sicherheit im situationalen Kontext</li> <li>5. Wissensgenerierung</li> <li>6. Organisations Lernen: Strategische Steuerung der Wissensgenerierung</li> <li>7. Fazit: Voraussetzungen für den sicheren Nachbetrieb und Rückbau</li> </ol> <p>Knowing That and Knowing How - Motivationale Aspekte sicherheitsbezogenen Wissensmanagements bei Nachbetrieb und Rückbau 2/13</p>
<p><b>n w</b> Fachhochschule Nordwestschweiz Hochschule für Angewandte Psychologie</p> <p>1. Vorbemerkung - Decommissioning: State of the art?</p> <ul style="list-style-type: none"> <li>• <b>Changemanagement und Strategieentwicklung von Erfüllung formaler Ansprüche zur Bildung operative Voraussetzung?</b> <ul style="list-style-type: none"> <li>–Organisationsaufbau (Struktur) &amp; Organisationsabläufe (Prozesse) ?</li> <li>–...</li> <li>–Recruiting-Strategie ?</li> <li>–Outplacement Stilllegung/Rückbau ?</li> <li>–Integration Fremdpersonal ?</li> <li>–....</li> <li>–<b>Gefahrenprävention</b> (Planung neuer Standards,...) ?</li> <li>–...</li> <li>–<b>Gefahrenbewältigung</b> der Anforderungen unbekannter Situationen ?</li> </ul> </li> </ul> <p>Knowing That and Knowing How - Motivationale Aspekte sicherheitsbezogenen Wissensmanagements bei Nachbetrieb und Rückbau 3/13</p>	<p><b>n w</b> Fachhochschule Nordwestschweiz Hochschule für Angewandte Psychologie</p> <p>1. Vorbemerkung - Alles eine Frage der Vision!</p> <p>Um genannte Aspekt „mit Leben zu füllen“, ist die Erhaltung/Förderung der Motivation wichtig!</p> <p>Dazu braucht es:</p> <ol style="list-style-type: none"> <li>1. Grundlegendes Verständnis der Situation</li> <li>2. Vision</li> <li>3. Partizipative Planung + Beratung/Forschung durch Externe</li> <li>4. Qualifizierte Begleitung durch Psycholog/inn/en</li> <li>5. Entwicklung eines qualifizierten Konzepts</li> </ol> <p>Knowing That and Knowing How - Motivationale Aspekte sicherheitsbezogenen Wissensmanagements bei Nachbetrieb und Rückbau 4/13</p>
<p><b>n w</b> Fachhochschule Nordwestschweiz Hochschule für Angewandte Psychologie</p> <p>2. Ausgangslage und Herausforderungen</p> <ul style="list-style-type: none"> <li>• <b>Nachbetrieb und Rückbau: motivational schwierige Perspektive</b> <ul style="list-style-type: none"> <li>◦ Angst vor Arbeitsplatzverlust, Sintern gesell. Ansehens und Veränderungen,...</li> <li>◦ oberstes Ziel einer Organisation, die Selbsterhaltung wird umgekehrt in „Selbstbesiegung“</li> <li>◦ Primärziel entfällt: keine Produktion</li> <li>◦ aus produktiver wird destruktive/dekonstruierende Tätigkeit</li> <li>◦ unklare Situationen drohen</li> </ul> </li> <li>• <b>Vision mit klaren Zielen erforderlich:</b> <ul style="list-style-type: none"> <li>◦ Nachbetrieb und Rückbau als Pionieraufgabe beschreiben</li> <li>◦ Ziele für sicheren Rückbau sind genau zu definieren!</li> <li>◦ Kompetenzaufbau /-erhalt – Wozu?</li> </ul> </li> <li>• <b>aus Changemanagement wird evolutionäres Lernen!</b></li> </ul> <p>Knowing That and Knowing How - Motivationale Aspekte sicherheitsbezogenen Wissensmanagements bei Nachbetrieb und Rückbau 5/13</p>	<p><b>n w</b> Fachhochschule Nordwestschweiz Hochschule für Angewandte Psychologie</p> <p>3. Rückbau als Pionieraufgabe</p> <ul style="list-style-type: none"> <li>• <b>Ausgangspunkt: Entwicklung einer Vision mit zentraler Strategie mit Fokus auf Pionierleistung</b> <ul style="list-style-type: none"> <li>◦ MA ihren wertvollen Beitrag erklären und veranschaulichen Berücksichtigung organisationalenkultureller Aspekte</li> <li>◦ Anpassung Nachbetriebs- und Rückbauleitbild</li> <li>◦ Reorganisation Organisationsstrukturen und –prozesse</li> <li>◦ Zielsetzung klären</li> </ul> </li> <li>• <b>Vorbereitung auf z.T. unerwartete und unbekannte Situationen</b> <ul style="list-style-type: none"> <li>◦ Erfahrungen beim Rückbau einholen und bei Planung berücksichtigen</li> <li>◦ MA einbeziehen (z.B. in Workshops mit Know-how-Trägern)</li> <li>◦ MA befähigen unklare Situationen im Team zu bewältigen</li> </ul> </li> </ul> <p>Knowing That and Knowing How - Motivationale Aspekte sicherheitsbezogenen Wissensmanagements bei Nachbetrieb und Rückbau 6/13</p>
<p><b>n w</b> Fachhochschule Nordwestschweiz Hochschule für Angewandte Psychologie</p> <p>4. Sicherheit im situationalen Kontext (Ritz, 2015; Ritz et al. 2013)</p> <p>Systemstatus: zuverlässig Systemqualität: Sicherheit</p> <p>Sicherheit</p> <p>Knowing That and Knowing How - Motivationale Aspekte sicherheitsbezogenen Wissensmanagements bei Nachbetrieb und Rückbau 7/13</p>	<p><b>n w</b> Fachhochschule Nordwestschweiz Hochschule für Angewandte Psychologie</p> <p>4. Situationaler Kontext: erforderliches Wissen und Kompetenzen</p> <ul style="list-style-type: none"> <li>• erwartete Situationen: zuverlässige Planung und Ausbildung; bestehendes Rückbauwissen (extern) einbeziehen und auf spez. Anlage modifizieren</li> <li>• <b>unerwartete Situationen:</b> bestehendes Rückbauwissen (extern) über Vorkommnisse, Probleme und Lösungen systematisieren und zuverlässige Pläne entwickeln</li> <li>• unerwartete und unbekannte Situationen: Personalentwicklung, sicherheitsbezogene Bewältigungsstrategien trainieren, sicherheitsbezogene Adaptationsfähigkeit im „Team“ fördern, kollektive Problemlösung zur Kompensation des „Unplanbaren“</li> </ul> <p>Wie aber spezifisches Wissen generieren und Kompetenzen fördern?</p> <p>Knowing That and Knowing How - Motivationale Aspekte sicherheitsbezogenen Wissensmanagements bei Nachbetrieb und Rückbau 8/13</p>



<p><b>n w</b> Fachhochschule Nordwestschweiz Hochschule für Angewandte Psychologie</p> <p>6. Prozess der Wissensgenerierung (Nonaka &amp; Takeuchi, 1995)</p> <p>Knowing That and Knowing How - Motivationale Aspekte sicherheitsbezogenen Wissensmanagements bei Nachbetrieb und Rückbau 9/13</p>	<p><b>n w</b> Fachhochschule Nordwestschweiz Hochschule für Angewandte Psychologie</p> <p>6. Prozessschritte (Nonaka &amp; Takeuchi, 1995)</p> <ol style="list-style-type: none"> <li><b>Sozialisation:</b> Erfahrungen teilen und dadurch implizites Wissen wie bspw. geteilte mentale Modelle oder technische Fähigkeiten erzeugen</li> <li><b>Externalisierung:</b> implizites Wissen artikulieren und in explizite Konzepte umwandeln; Externalisierung als Schlüsselprozess bei Wissensumwandlung; neue explizite Konzepte werden aus implizitem Wissen geschaffen. Mentale Modelle und Kompetenzen werden zu alltagstauglichen Konzepten.</li> <li><b>Kombination:</b> Konzepte in ein Wissenssystem einordnen, d.h. isolierte Teile zu einem gemeinsamen Ganzen verbinden; Personen tauschen und kombinieren Wissen z.B. über Dokumente, Treffen oder elektronische Kommunikationsnetzwerke. Neues Wissen kann vor allem durch Kombinieren, Hinzufügen, Sortieren oder Kategorisieren entstehen. Zentral ist dabei die Reflexion der zu kombinierenden Inhalten.</li> <li><b>Internalisierung:</b> explizites Wissen zu implizitem Wissen verinnerlichen; stark mit dem Begriff „learning by doing“ verbunden; Sobald Erfahrungen durch Sozialisierung, Externalisierung und Kombination in individuelle Wissensbasen durch mentale Modelle oder technisches «Know-how» internalisiert werden, entsteht operative Handlungsfähigkeit.</li> </ol> <p>Knowing That and Knowing How - Motivationale Aspekte sicherheitsbezogenen Wissensmanagements bei Nachbetrieb und Rückbau 10/13</p>
<p><b>n w</b> Fachhochschule Nordwestschweiz Hochschule für Angewandte Psychologie</p> <p>6. Organisationsales Lernen (Ritz, 2015, Ritz, 2016, Argyris &amp; Schön, 1996) als Strategische Steuerung der Wissensgenerierung</p> <p>3. Deutero Lernen: Lernen, wie und was in der Organisation gelernt wird</p> <p>Knowing That and Knowing How - Motivationale Aspekte sicherheitsbezogenen Wissensmanagements bei Nachbetrieb und Rückbau 13/13</p>	<p><b>n w</b> Fachhochschule Nordwestschweiz Hochschule für Angewandte Psychologie</p> <p>6. Fazit: Voraussetzungen für sichereren Nachbetrieb &amp; Rückbau</p> <ul style="list-style-type: none"> <li><b>Motivation:</b> Strategie und Vision – Rückbau als Pioneraufgabe       <ul style="list-style-type: none"> <li>Organisationskultur einbeziehen (Artefakte, Werte, Grundannahmen)</li> </ul> </li> <li><b>Sicherheit:</b> Planbares zuverlässig planen, Unplanbarem durch Förderung von Adaptationsfähigkeit begegnen</li> <li><b>Wissensmanagement:</b> Prozess mit Workshops, Trainings, Gremien...etc. implementieren, um stetig implizites in explizites Wissen zu überführen</li> <li><b>Organisationales Lernen:</b> Aktiv auf spezifische Stärken des Menschen fokussieren</li> <li><b>Was tun:</b> <ol style="list-style-type: none"> <li>1) Know-How generieren</li> <li>2) Know-How-Entwicklung steuern</li> <li>3) Know-How speichern</li> <li>4) Rückbau-Kompetenz vermarkten!</li> </ol> </li> </ul> <p>Knowing That and Knowing How - Motivationale Aspekte sicherheitsbezogenen Wissensmanagements bei Nachbetrieb und Rückbau 12/13</p>

## Motivationale Aspekte sicherheitsbezogenen Wissensmanagements bei Nachbetrieb und Rückbau

Nuclear operators are challenged to prepare the organisation and its staff for decommissioning. Especially, the design of the changing points in the organisation will be critical: from the operational phase to post-operational phase and from post-operational phase to decommissioning. The organisation and their employees have to fulfil strategic and motivational efforts, in order to manage these changes effectively. While operating in these new phases, uncertainty will occur to a high degree, in terms of not pre-planable situations. Required organisational standards - like process-descriptions, procedures or roles – will often not fit to specific situational requirements.

In order to maintain system safety (occupational and nuclear safety) new knowledge has to be generated and combined with existing knowledge. To this end, motivation is an essential basis to lead behaviour to a high level of safety performance. Therefore, in this contribution, scientific approaches in the areas of motivation, knowledge management, change management, organizational learning, resilience and organizational culture are condensed into an application-oriented framework. This framework deals with the appropriate conditions that have to be established to organize a high level of safety performance during the different phases of change, in order to reach decommissioning successfully.

Furthermore, the change process will be described as a chance. Planning and its implementation can deliver valuable aspects, how the strategies of hazard prevention and hazard coping can be balanced in practice. By collecting relevant data and their systematization, marketable know-how could be generated, that will be needed for further (world-wide) decommissioning-projects.

The key to this is, to regard human behaviour as a source of safety. Successful human adaptations are needed to solve situation specific problems, with which the control under varying conditions can be kept. The capture of this adaptions in relation to the demands of specific situations, leads to knowledge, which is useful to describe new operating procedures, e.g. in terms of standards for decommissioning. An underlying vision, that is allowing adaptions and learning of them, can be useful for the design of conditions of the decommissioning in general.



## Specific implications of decommissioning on radiation protection

	 <p>Occupational radiation protection during the decommissioning of Nuclear Power Plants</p> <p>Radiation Protection Workshop</p> <p>April 8, 2016</p> <p style="text-align: right;">cepn</p>	<p style="text-align: right;">Content</p> <ul style="list-style-type: none"> <li>■ Introduction</li> <li>■ Operation versus decommissioning</li> <li>■ Radiological Characterisation</li> <li>■ Management of external exposures</li> <li>■ Management of internal exposures</li> <li>■ Concluding remarks</li> </ul> <p style="text-align: right;">2</p>
	<p style="text-align: center;"><b>Introduction</b></p> <ul style="list-style-type: none"> <li>■ Decommissioning is a new stage in the life of the facility that will progressively lead to the breach of all containment barriers and thus change the 'radiological' conditions.</li> <li>■ All requirements for occupational radiation protection apply to the decommissioning stage: <ul style="list-style-type: none"> <li>■ Proper workers' training,</li> <li>■ Individual and collective monitoring,</li> <li>■ Dose limits,</li> <li>■ Maintain exposures ALARA,</li> <li>■ Etc.</li> </ul> </li> <li>■ An important difference: there is probably an increase of the potential for internal exposure while some (most) operators and (or) regulatory bodies expect 0 mSv from internal exposures.</li> </ul> <p style="text-align: right;">3</p>	<p style="text-align: center;"><b>Operation versus decommissioning</b></p> <ul style="list-style-type: none"> <li>■ During operation, except for specific jobs (SGR for instance), RP staff has many feedback data to prepare jobs in the RCA: <ul style="list-style-type: none"> <li>■ Exposure duration,</li> <li>■ Accurate dose rate,</li> <li>■ Circuit contamination,</li> <li>■ Experienced staff,</li> <li>■ Etc.</li> </ul> </li> <li>■ Ability to accurately plan expected occupational exposures and to implement efficient dose reduction actions (shielding, organization, just in-time training, decontamination, etc.).</li> <li>■ Different situation when planning decommissioning activities (also depending on the decommissioning strategy e.g. immediate versus safe store).</li> </ul> <p style="text-align: right;">4</p>
	<p style="text-align: center;"><b>Operation versus decommissioning</b></p> <ul style="list-style-type: none"> <li>■ During decommissioning: <ul style="list-style-type: none"> <li>■ Difficulty for estimating exposure duration,</li> <li>■ Dose rate may evolve during the work,</li> <li>■ Pipe/component cutting: increase potential for contamination dispersion in the working area,</li> <li>■ New jobs/tasks,</li> <li>■ Etc.</li> </ul> </li> <li>■ Difficult to assess exposures and thus to implement adequate protections means. In some cases: overestimate of collective dose which may lead to a non appropriate level of protection.</li> <li>■ Work duration may be influenced by a lack of knowledge of mechanical and physical properties of components (thickness, etc.) leading to an increase of external exposures. RP performances are influenced by a lack of data which are not only related to radiological characterisation.</li> </ul> <p style="text-align: right;">5</p>	<p style="text-align: center;"><b>Operation versus decommissioning</b></p> <ul style="list-style-type: none"> <li>■ Well known but: it's very important to keep operating staff in order to prepare and achieve an efficient decommissioning program: <ul style="list-style-type: none"> <li>■ Operating knowledge of events that may influence radiological conditions in which decommissioning works take place (fuel claddings, leakage, component replacement, etc.).</li> </ul> </li> </ul> <p style="text-align: right;">6</p>
	<p style="text-align: center;"><b>Radiological Characterisation</b></p> <ul style="list-style-type: none"> <li>■ A detailed radiological characterisation is required for : <ul style="list-style-type: none"> <li>■ An effective management of radioactive wastes streams during the decommissioning project,</li> <li>■ An effective management of workers radiological protection.</li> </ul> </li> <li>■ It includes: <ul style="list-style-type: none"> <li>■ Components and pipe (primary circuit) sampling and analysis, <ul style="list-style-type: none"> <li>• Potential for activity re-suspension during cutting,</li> <li>• Mechanical/physical properties.</li> </ul> </li> <li>■ Detailed mapping of all RCA locals with dose rate measurements and contamination measurement (fixed and not fixed), <ul style="list-style-type: none"> <li>• Assess collective exposure,</li> <li>• Plan individual and collective protective equipment.</li> </ul> </li> <li>■ 3D pictures with gamma camera (identify hot spots), <ul style="list-style-type: none"> <li>• Favour workers training,</li> <li>• Efficient pre-job briefing.</li> </ul> </li> </ul> </li> </ul> <p style="text-align: right;">7</p>	<p style="text-align: center;"><b>Radiological Characterisation San Onofre 1</b></p> <ul style="list-style-type: none"> <li>■ Characterisation plan: 1 full year before starting the work. <ul style="list-style-type: none"> <li>■ 50 to 60 samples per circuit. Analysis: <math>\alpha</math> and <math>\gamma</math> spectrometry.</li> <li>■ For all samples: pictures + GPS.</li> <li>■ Videos of complex area for workers training and briefing.</li> <li>■ Contamination: 5 to 10 samples for a 20 m<sup>2</sup> area.</li> </ul> </li> </ul> <p style="text-align: right;">8</p>



	<h3 style="text-align: center;">Decontamination</h3> <ul style="list-style-type: none"> <li>■ Based on characterisation results: assess the need for full system or component decontamination:           <ul style="list-style-type: none"> <li>■ Decrease dose rate and thus collective exposure,</li> <li>■ Decrease of residual contamination allowing to meet clearance criteria (according to national regulations) and decrease radioactive waste storage costs.</li> </ul> </li> <li>■ Several vendors (AREVA CORD, Westinghouse, etc.) and process.</li> <li>■ Implementation of such process leads to workers exposure. Depending on the duration of decontamination:           <ul style="list-style-type: none"> <li>■ Collective dose higher than 100 H.mSv,</li> <li>■ Production of contaminated resins to managed as radioactive wastes.</li> </ul> </li> </ul>	 <h3 style="text-align: center;">Management of external exposures</h3> <ul style="list-style-type: none"> <li>■ Individual monitoring:           <ul style="list-style-type: none"> <li>■ Use of passive and operational dosimeters as for operation.</li> </ul> </li> <li>■ It may be difficult to assess collective dose for some task requiring intensive working hours (several 1000) in very low dose rate areas (a few <math>\mu\text{Sv.h}^{-1}</math>). During the planning, calculated collective dose in the range of 10 to 50 man.mSv but actual recorded dose may be closed to 0.           <ul style="list-style-type: none"> <li>■ May be an issue when discussing with regulators differences between planned and actual exposures.</li> </ul> </li> </ul>																																																																														
	<h3 style="text-align: center;">Management of external exposures Reactor vessel segmentation</h3> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>Plant</th> <th>Cutting Method</th> <th>RPV Activity Ci (Bq)</th> <th>Cutting Length ft (m)</th> <th>Radiation Exposure</th> <th>Waste Volume m³</th> <th>Filtration Flowrate gpm (lpm)</th> </tr> </thead> <tbody> <tr> <td>Yankee Rowe</td> <td>Plasma Arc Metal Disintegration Machining (MDM)</td> <td>0.9 M Ci (3.4 E16 Bq)</td> <td>Segmented All Internals</td> <td>100 rem (1 Sv)</td> <td>Not Comparable. All of Internals except GTCC shipped as Waste</td> <td>75 gpm (284 lpm)</td> </tr> <tr> <td>Conn Yankee</td> <td>Abrasive Water Jet MDM</td> <td>0.6 M Ci (3.0 E16 Bq)</td> <td>1800 ft (550 m)</td> <td>205 rem (2.05 Sv)</td> <td>1250 ft³ (35.4 m³)</td> <td>Approx 250 gpm (950 lpm)</td> </tr> <tr> <td>Maine Yankee</td> <td>Ultra High Pressure Water Jet Mechanical Cutting</td> <td>2 M Ci (7.4 E16 Bq)</td> <td>1170 ft (355 m)</td> <td>50 rem (0.5 Sv)</td> <td>1700 ft³ (48 m³)</td> <td>1000 gpm (3,785 lpm)</td> </tr> <tr> <td>Songs Unit 1</td> <td>Abrasive Water Jet MDM</td> <td>0.4 M Ci (1.4 E16 Bq)</td> <td>813 ft (248 m)</td> <td>23 rem (0.23 Sv)</td> <td>254 ft³ (7.2 m³)</td> <td>1,500 gpm (5,700 lpm)</td> </tr> <tr> <td>Rancho Seco</td> <td>Mechanical Cutting Hydraulic Press Separation</td> <td>0.07 M Ci (2.7 E15 Bq)</td> <td>Cut into Large Pieces</td> <td>20 rem (0.2 Sv)</td> <td>Approximately 1,130 ft³ (32 m³), All of Internals except GTCC shipped as Waste</td> <td>Not Available</td> </tr> </tbody> </table>	Plant	Cutting Method	RPV Activity Ci (Bq)	Cutting Length ft (m)	Radiation Exposure	Waste Volume m³	Filtration Flowrate gpm (lpm)	Yankee Rowe	Plasma Arc Metal Disintegration Machining (MDM)	0.9 M Ci (3.4 E16 Bq)	Segmented All Internals	100 rem (1 Sv)	Not Comparable. All of Internals except GTCC shipped as Waste	75 gpm (284 lpm)	Conn Yankee	Abrasive Water Jet MDM	0.6 M Ci (3.0 E16 Bq)	1800 ft (550 m)	205 rem (2.05 Sv)	1250 ft³ (35.4 m³)	Approx 250 gpm (950 lpm)	Maine Yankee	Ultra High Pressure Water Jet Mechanical Cutting	2 M Ci (7.4 E16 Bq)	1170 ft (355 m)	50 rem (0.5 Sv)	1700 ft³ (48 m³)	1000 gpm (3,785 lpm)	Songs Unit 1	Abrasive Water Jet MDM	0.4 M Ci (1.4 E16 Bq)	813 ft (248 m)	23 rem (0.23 Sv)	254 ft³ (7.2 m³)	1,500 gpm (5,700 lpm)	Rancho Seco	Mechanical Cutting Hydraulic Press Separation	0.07 M Ci (2.7 E15 Bq)	Cut into Large Pieces	20 rem (0.2 Sv)	Approximately 1,130 ft³ (32 m³), All of Internals except GTCC shipped as Waste	Not Available	 <h3 style="text-align: center;">Management of external exposures SONGS 1</h3> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>Year</th> <th>Time in RCA (h)</th> <th>Dose Col. (H.Sv)</th> </tr> </thead> <tbody> <tr> <td>1999</td> <td>12 098</td> <td>0,163</td> </tr> <tr> <td>2000</td> <td>116 134</td> <td>0,717</td> </tr> <tr> <td>2001</td> <td>184 790</td> <td>0,599</td> </tr> <tr> <td>2002</td> <td>143 430</td> <td>0,618</td> </tr> <tr> <td>2003</td> <td>167 330</td> <td>0,361</td> </tr> <tr> <td>2004</td> <td>138 556</td> <td>0,173</td> </tr> <tr> <td>2005</td> <td>152 534</td> <td>0,195</td> </tr> <tr> <td>2006</td> <td>187 338</td> <td>0,174</td> </tr> <tr> <td>2007</td> <td>171 080</td> <td>0,003</td> </tr> <tr> <td>2008</td> <td>75 156</td> <td>0</td> </tr> <tr> <td>Total</td> <td>1 102 210</td> <td>3,003</td> </tr> </tbody> </table>	Year	Time in RCA (h)	Dose Col. (H.Sv)	1999	12 098	0,163	2000	116 134	0,717	2001	184 790	0,599	2002	143 430	0,618	2003	167 330	0,361	2004	138 556	0,173	2005	152 534	0,195	2006	187 338	0,174	2007	171 080	0,003	2008	75 156	0	Total	1 102 210	3,003
Plant	Cutting Method	RPV Activity Ci (Bq)	Cutting Length ft (m)	Radiation Exposure	Waste Volume m³	Filtration Flowrate gpm (lpm)																																																																										
Yankee Rowe	Plasma Arc Metal Disintegration Machining (MDM)	0.9 M Ci (3.4 E16 Bq)	Segmented All Internals	100 rem (1 Sv)	Not Comparable. All of Internals except GTCC shipped as Waste	75 gpm (284 lpm)																																																																										
Conn Yankee	Abrasive Water Jet MDM	0.6 M Ci (3.0 E16 Bq)	1800 ft (550 m)	205 rem (2.05 Sv)	1250 ft³ (35.4 m³)	Approx 250 gpm (950 lpm)																																																																										
Maine Yankee	Ultra High Pressure Water Jet Mechanical Cutting	2 M Ci (7.4 E16 Bq)	1170 ft (355 m)	50 rem (0.5 Sv)	1700 ft³ (48 m³)	1000 gpm (3,785 lpm)																																																																										
Songs Unit 1	Abrasive Water Jet MDM	0.4 M Ci (1.4 E16 Bq)	813 ft (248 m)	23 rem (0.23 Sv)	254 ft³ (7.2 m³)	1,500 gpm (5,700 lpm)																																																																										
Rancho Seco	Mechanical Cutting Hydraulic Press Separation	0.07 M Ci (2.7 E15 Bq)	Cut into Large Pieces	20 rem (0.2 Sv)	Approximately 1,130 ft³ (32 m³), All of Internals except GTCC shipped as Waste	Not Available																																																																										
Year	Time in RCA (h)	Dose Col. (H.Sv)																																																																														
1999	12 098	0,163																																																																														
2000	116 134	0,717																																																																														
2001	184 790	0,599																																																																														
2002	143 430	0,618																																																																														
2003	167 330	0,361																																																																														
2004	138 556	0,173																																																																														
2005	152 534	0,195																																																																														
2006	187 338	0,174																																																																														
2007	171 080	0,003																																																																														
2008	75 156	0																																																																														
Total	1 102 210	3,003																																																																														
	<h3 style="text-align: center;">Management of internal exposures</h3> <ul style="list-style-type: none"> <li>■ Different approaches:           <ul style="list-style-type: none"> <li>■ Favour an intensive decontamination strategy allowing workers to perform their tasks in non contaminated areas:               <ul style="list-style-type: none"> <li>• Require skilled decon. workers,</li> <li>• Get ride of contamination of fixed residual contamination with sprays, paints, etc.</li> </ul> </li> <li>■ Protect workers against internal contamination:               <ul style="list-style-type: none"> <li>• Individual ventilated suits,</li> <li>• Respiratory masks,</li> <li>• Engineering barriers,</li> <li>• Individual monitoring:                   <ul style="list-style-type: none"> <li>• Biological analysis,</li> <li>• Tissue,</li> <li>• Personal air samplers.</li> </ul> </li> </ul> </li> </ul> </li> <li>■ With the second strategy, need for dressing and undressing training and increase in work duration (+20 to 30%).</li> </ul>	 <h3 style="text-align: center;">Management of internal exposures Humboldt Bay</h3> <ul style="list-style-type: none"> <li>■ Boiling water reactor (BWR) which experienced numerous fuel cladding during operation. Consequence: high level of contamination and <math>\beta/\gamma/\alpha</math> ratio close to 1:1.       <ul style="list-style-type: none"> <li>■ All workers wear a personal air sampler and filter analysis is used to assess internal exposure,</li> <li>■ Favour air filtering masks rather than ventilated suits,</li> <li>■ Important work to protect hands and forearms: contamination of blood with alpha emitters is 10 times worst than inhalation in terms of dose,</li> <li>■ Area monitoring: fixed air samplers and continuous air monitoring monitors (MGP EDGAR) - but difficult to use in dusty atmosphere -,</li> <li>■ Only mechanical cutting (no hot cutting techniques) to prevent activity re-suspension.</li> </ul> </li> </ul>																																																																														
	<h3 style="text-align: center;">Other occupational risk</h3> <ul style="list-style-type: none"> <li>■ Attention must be paid to the management of risk other than ionising radiation, for instance asbestos or lead exposures.       <ul style="list-style-type: none"> <li>■ Some difficulties met in France for protection against asbestos in RCA as regulatory requirement for a shower immediately after working in asbestos areas.</li> </ul> </li> <li>■ Characterisation strategy must include these risks.</li> </ul>	 <h3 style="text-align: center;">Concluding remarks</h3> <ul style="list-style-type: none"> <li>■ Decommissioning generally leads to an increase of internal exposure risk requiring a particular involvement of the RP staff as well as dedicated training of workers.</li> <li>■ Characterisation strategy is crucial in order to properly manage radiation protection and radioactive waste streams.</li> <li>■ Full or partial system decontamination during the transition phase may help to reduce dose rates and contamination.</li> <li>■ Importance of information sharing between operators involved in NPP decommissioning in order to identify best practices (ISOE WG DECOM, <a href="http://www.lsoe-network.net">www.lsoe-network.net</a>).</li> </ul>																																																																														



## **Radioprotection des travailleurs lors du démantèlement des installations nucléaires**

[Ludovic.Vaillant@cepn.asso.fr](mailto:Ludovic.Vaillant@cepn.asso.fr)

CEPN

28 rue de la Redoute

92 260 Fontenay-aux-Roses

Le nombre de centrales nucléaires mises à l'arrêt définitif est croissant en Europe et aux Etats-Unis. Le démantèlement de ces installations présente des risques particuliers par rapport à la phase d'exploitation qu'il convient d'anticiper et de gérer afin d'assurer un niveau optimal de protection des intervenants.

La préparation et la réalisation de travaux de maintenance dans les installations nucléaires et les centrales électronucléaires en particulier s'appuient sur une connaissance approfondie de l'état de l'installation et des conditions radiologiques et sur l'existence d'un retour d'expérience solide après plusieurs décennies d'exploitation.

Lors du démantèlement de l'installation, les intervenants réalisent des activités sans disposer de retour d'expérience et dans un environnement évolutif, ce qui complexifie la préparation des travaux et le choix des moyens d'optimisation de la radioprotection. Par ailleurs, la rupture progressive des barrières de confinement (découpe des tuyauteries et des gros composants) génère un risque d'exposition interne plus important qu'en phase d'exploitation.

Une gestion adaptée de ces risques repose en premier lieu sur une caractérisation précise de l'installation, caractérisation qui présente également un intérêt pour la gestion des flux de déchets radioactifs générés tout au long du démantèlement de l'installation. Cette caractérisation s'appuie sur des mesures de débits de dose, des prélèvements et analyses (spectrométrie alpha et gamma) de circuits, la réalisation de frottis, l'utilisation de gamma caméra, etc. Il est également important de s'appuyer sur une connaissance solide de l'historique d'exploitation de l'installation et des événements ayant pu impacter les conditions d'intervention (rupture de gaine de combustible, fuites sur le circuit primaire, etc.).

Les données fournies par la caractérisation constituent une base solide permettant de juger de l'utilité de la décontamination chimique des circuits et des composants. Ces données permettent également d'élaborer des prévisionnels de dose pour les différentes opérations de démantèlement et de mettre en œuvre des moyens de prévention du risque de contamination interne (port de masque à air filtrant, tenue étanche ventilée, mise en place de sas de confinement, etc.). La formation à la radioprotection des intervenants doit inclure ces spécificités.

Il convient d'intégrer la gestion du risque radiologique des intervenants dans le contexte plus large de prévention des risques (amiante, plomb, sécurité classique, etc.) en veillant à un niveau de protection optimale des travailleurs.

Le partage d'expérience avec les exploitants ayant déjà réalisé des démantèlements de centrales nucléaires est un facteur important d'acquisition de compétence et d'expérience afin d'identifier les meilleures pratiques en termes de radioprotection des intervenants sur ce type d'activité. Dans cet esprit, le réseau ISOE a mis en place un groupe de travail spécifique ([www.isoegroup.net](http://www.isoegroup.net)).



## Decommissioning and medical aspects

### Arbeitsmedizinische Erfahrungen beim Rückbau des Kernkraftwerkes Würgassen

Dr. med. Klaus Rose  
Facharzt für Allgemeinmedizin-Betriebsmedizin  
Neue Strasse 37, D-37699 Fürstenberg  
Telefon: 0049-5271-4488  
E-Mail: doc-rose@gmx.de

### Rückbau des Kernkraftwerks Würgassen



### Zwischenlager des Kernkraftwerks Würgassen




### Alpha-Inkorporationen

- Zwischen 1998 und 2013 wurden über 7000 Ausscheidungsproben ausgewertet.
- Der überwiegende Teil der Ausscheidungsproben zeigten keinen Befund.
- Der Grenzwert für eine Inkorporation mit Alphanukliden in der Probe betrug 1,5 mBq/d.
- Die meisten betrachteten Befunde führten zu einer effektiven Dosis von <50 µSv.
- Im gesamten Überwachungszeitraum gab es eine Inkorporation mit einer effektiven Dosis von ca. 0,85 mSv.

### Kurzbiographie des Kernkraftwerks Würgassen

- Errichtung 19.07.1967 Antrag auf Errichtung und Betrieb
- 19.01.1968 Baubeginn
- 18.12.1971 Erste nukleare Stromerzeugung
- Stromerzeugung bis August 1994 Rund 73 Milliarden KWh
- Stilllegung 29.05.1995 Stilllegungsbeschluss
- 25.09.1995 Antrag auf Stilllegung und Rückbauphase I


### Rückbau des Kernkraftwerks Würgassen




### Erfahrungen beim Rückbau des Kernkraftwerks Würgassen

- Alpha-Inkorporation
- Gefahrstoffe (z.B. PCB)
- Unfallgeschehen
- Fazit


### Alpha-Inkorporationen



## Alpha-Inkorporationen



## Alpha-Inkorporationen



## Gefahrstoffe

### PCB – wie tritt es auf?

- PCB wird auf zwei Pfaden freigesetzt
  - Staubgebunden kann PCB bei allen mechanischen Eingriffen in die Gebäudestruktur freigesetzt werden (Stemmen, Fräsen, Bohren, ...)
  - In der gasförmigen Phase wird PCB bei wärmeentwickelnden Abtragsverfahren freigesetzt (Fräsen, Schleifen, ...)

## Gefahrstoffe

### Ermittlung der PCB-Belastung im Kernkraftwerk Würgassen


- Oberflächenabtrag durch eine modifizierte Schleifscheibe (Abtragtiefe jeweils in 3mm Schritten)
- Boden, Wände und Decken in 3 Schritten bis max. 9mm Tiefe
- Dekontanstrich vom Probenahmeort separat abgetragen und ausgewertet
- Vergleich der PCB-Verteilung in der Gebäudestruktur mit und ohne Dekontanstrich
- 8 Proben mit erhöhter Aktivität (> 10 Bq/g) konnten nicht ausgewertet werden
- Berücksichtigung der Gebäudestruktur in den Bauteilen BT 1,2, 2a, 3, 6 und 7

## Gefahrstoffe

### Ergebnisse der PCB-Belastung im Kernkraftwerk Würgassen


- PCB befindet sich dominant im Dekontanstrich.
- Die maximale PCB-Konzentration von 20850 mg/kgOS wurde in der Dekontbeschichtung im BT 2, Raum 2.110 ermittelt.
- Die maximale PCB-Konzentration an der Oberfläche der Gebäudestruktur (0-3 mm) beträgt 2450 mg/kgOS (BT 2, Raum 2.133).
- Die PCB-Konzentration in der Gebäudestruktur ohne Dekontanstrich ist gering (ab 3 mm Tiefe < 10 mg/kgOS).
- Zusätzliche Proben sind zur Ermittlung der PCB-Konzentration in anderen Bereichen notwendig (z.B. BT 65, Probe aus 6 mm Tiefe = 1,1 mg/kgOS).

## Gefahrstoffe



## Gefahrstoffe

Alle untersuchten Räume im KB des KWW (Gebäudestruktur ohne Dekontbeschichtung)



## Gefahrstoffe

### Ableitung der Abluft aus PCB-Arbeitsbereichen

- Staubgebundene PCB-Emissionen
  - Beim Einsatz von Dekonverfahren mit lediglich staubgebundenen PCB ist eine Arbeitsplatzabsaugung zur Staubminderung mit Rückführung der Abluft in die Raumluft des Arbeitsbereiches möglich (Einsatz eines Dust-Control mit H13-Filterung).
- Wärmeentwickelnde Verfahren
  - Beim Einsatz von wärmeentwickelnden Verfahren darf die Abluft aus der Arbeitsplatzabsaugung nicht in die Raumluft des Arbeitsbereich zurückgeführt werden. Die Ableitung der Abluft erfolgt über das Filtermobil direkt in die Fortluft.



## Gefahrstoffe

### Beispielhafter Arbeitsschutz bei Sanierung mit PCB-Konzentration in der Raumluft

- Ermittelte PCB-Konzentration in der Raumluft während Frasarbeiten: 5,9 µg/m³ (< 1/100 AGW)
- Arbeitsschutz:
  - Microfaserringzug, Überschuhe, Baumwoll- und Nitrilhandschuhe, Vollmaske, P3-Filter, Arbeitsplatz- und werkzeugbezogene Absaugung (Dust-Controll, H13-Abscheidung = 99,95%, Rückführung der Luft in den Arbeitsbereich)

## Gefahrstoffe

### Zusammenfassung


- In den Dekontanstrichen bis in die 80'er Jahre hinein finden sich erhebliche PCB-Konzentrationen. Verwertbare Informationen hierüber liegen nicht mehr vor. Verbot in offenen Systemen ab 1978, generell ab 1989 in Deutschland, in der Schweiz 1972 bzw. 1986.
- Ab 6 mm Tiefe sind die Konzentrationen so gering, dass die abgetragene Betonstruktur deponierbar ist.
- Unter Verwendung von üblichen Absaugungen waren die staub- und gasförmigen Konzentrationen bei 1/100 und weniger des AGW.
- Der radiologisch bedingte Arbeitsschutz reicht für die Sanierung der PCB-Belastung in der Arbeitsbereichen aus.
- Die Deponierung von gemischten radioaktiven Abfall mit PCB-Anteilen zur Endlagerung ist abschließend geklärt. Derzeit befinden sich diese Gebinde noch im Zwischenlager des KWW Würgassen.

AGW = Arbeitsplatzgrenzwert


## Unfallgeschehen

- Das Unfallgeschehen entspricht dem Hochbaugewerbe (Zunahme von Hand- und Augenverletzungen)
- Dem Einsatz der PSA kommt entscheidende Bedeutung zu
- Problematisch sind minderqualifizierte Mitarbeiter von Fremdfirmen

## Unfallgeschehen



## Unfallgeschehen



## Unfallgeschehen



## Unfallgeschehen

### Arbeiten mit Absturzgefahr

- Die allgemeinen Arbeiten mit Absturzgefahr nehmen mit Fortschreiten der Rückbauarbeiten deutlich zu.
- Rückbaubegleitend ist die Sicherung der Arbeitsplätze gegen Absturzgefahren sehr wichtig.
- Im Zuge des Rückbaus muss ein vermehrtes Augenmerk auf die Beschaffung von PSA gegen Absturz gesetzt werden.
- Durch einen erhöhten Schulungsaufwand muss allen Mitarbeitern die Problematik des Hängtraumas vermittelt werden.

## Unfallgeschehen

### Hängtrauma

- Unter Hängtrauma versteht man einen Kreislaufzusammenbruch aufgrund des freien, bewegunglosen und aufrechten Hängens in einem Auffanggurt bzw. Sicherungsgeschirr. Bereits nach wenigen Minuten kann die Bewusstlosigkeit eintreten.




- Nach 2 – 12 Minuten treten Herzrhythmusstörungen und Bewusstlosigkeit auf.
- Nach einer 10-minütigen Bewusstlosigkeit kann bereits der Tod eintreten.
- Nach ca. 25 Minuten „freiem Hängen“ tritt mit hoher Wahrscheinlichkeit, auch nach erfolgreicher Rettung, der Tod ein.



<h2>Unfallgeschehen</h2> <ul style="list-style-type: none"> <li>➤ Die in Frage kommenden Mitarbeiter sollten geschult werden, während des Hängens möglichst die Beine zu bewegen.</li> <li>➤ Ein abgestürzter Mitarbeiter, der frei und aufrecht im Rettungsgeschirr hängt, ist ein medizinischer Notfall.</li> <li>➤ Der Ausdruck „prompte Bergung“ meint „sofortiges Beenden des Hängens“.</li> <li>➤ Retter brauchen ein Spezialtraining mit Verständnis für die physiologischen Vorgänge. Verletzte unbedingt in Oberkörperhochlage bzw. Kauerstellung bringen.</li> <li>➤ Das Risiko des Hängetraumas ist für Unerfahrene nicht zu ermessen.</li> </ul>	<h2>Unfallgeschehen</h2> <p><b>Voraussetzungen zum Tragen von PSA gegen Absturz im KWW</b></p> <ul style="list-style-type: none"> <li>➤ Technische und organisatorische Maßnahmen sind nicht möglich oder stehen in keinem vertretbarem Verhältnis.</li> <li>➤ Ausgabe von PSA gegen Absturz erfolgt nur an hierzu berechtigtes Personal</li> <li>➤ Unterweisung im Umgang mit PSA gegen Absturz, nicht älter als 1 Jahr.</li> <li>➤ Gültige G41-Untersuchung</li> <li>➤ Keine Arbeiten mit PSA gegen Absturz, wenn sich kein sachkundiger Mitarbeiter auf der Anlage aufhält.</li> </ul>
<h2>Fazit</h2> <ul style="list-style-type: none"> <li>➤ Sinkende Strahlenbelastung, nur sehr geringe Alpha-Inkorporationen (50-Jahre Folgedosis max. 5–10 µSv).</li> <li>➤ Unerwartete Gefahrstoffe, z.B. versehentliches Zersägen von bleihaltigen Einbauten, PCB, Asbest, ...</li> <li>➤ Steigende Belastung der Restbelegschaft: <ul style="list-style-type: none"> <li>➤ Zeitlich</li> <li>➤ Inhaltlich: zunehmende ausbildungs- und tätigkeitsfremde Arbeiten</li> <li>➤ Burn-Out Risiko steigt</li> <li>➤ Neue Herausforderungen: G41, Höhenrettung, Arbeiten mit Sicherheitsgeschirr, Hängetrauma</li> <li>➤ Lüftungstechnik (O2-Vol.% niedrigste Messung: 19%), Beleuchtung</li> <li>➤ Problemreich Fremdfirmen</li> <li>➤ Nacharbeit</li> <li>➤ Anschlagen von Lasten</li> <li>➤ Individuelle Gefährdungsanalyse</li> <li>➤ Aufbewahrungsfristen</li> </ul> </li> </ul>	<p><b>Danke für ihre Aufmerksamkeit.</b></p>



## Decommissioning and clearance

<p><b>KSR-Workshop at BERN, 8 April 2016</b></p>  <p><b>Content</b></p> <ul style="list-style-type: none"> <li>1. Definition</li> <li>2. Dose Concept and Derived Values</li> <li>3. Regulations in Germany</li> <li>4. Why Supervision for Clearance?</li> <li>5. IAEA Regulations</li> <li>6. Importance of Clearance for Decommissioning</li> <li>7. Planned Regulations for Switzerland</li> <li>8. Chances to Reduce the Strong Dependence from Modifications of Clearance Regulations</li> <li>9. Conclusion</li> </ul> <p><b>2 Dose Concept and Derived Values</b></p> <p>IAEA standard 1988: some mrem are negligible (de minimis concept)</p> <p>IAEA RS-G-1.7 2004 =&gt; IAEA BSS 2014 nuclide specific values for general clearance</p> <p>EC BSS 2015 =&gt; nat. legislation 2018</p> <p>Revision of RS-G-1.7 ??? surface specific values, values for specific clearance</p> <p><b>3 Regulations in Germany</b></p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th rowspan="2">Nucleus</th> <th colspan="2">Exemption limit</th> <th rowspan="2">Surface contamination</th> <th colspan="3">General Clearance of</th> <th colspan="2">Specific Clearance of</th> <th rowspan="2">Half-life</th> </tr> <tr> <th>Activity [Bq]</th> <th>Specific activity [Bq/g]</th> <th>Solid substances, liquids, with the exception of column 6 [Bq/m²]</th> <th>Building rubble, excavated soil amounts over 1,000 Mg/a [Bq/g]</th> <th>Buildings for reuse or continued use [Bq/cm²]</th> <th>Solid substances and liquids for disposal [Bq/m²]</th> <th>Buildings for demolition [Bq/cm²]</th> <th>Metal Scrap for Recycling [Bq/g]</th> </tr> </thead> <tbody> <tr> <td>H-3</td> <td>1 E+7</td> <td>1 E+9</td> <td>100</td> <td>1 E+3</td> <td>60</td> <td>3</td> <td>1 E+3</td> <td>4 E+3</td> <td>1 E+3</td> <td>12.3 a</td> </tr> <tr> <td>Bk-7</td> <td>1 E+7</td> <td>1 E+9</td> <td>100</td> <td>30</td> <td>30</td> <td>2</td> <td>80</td> <td>200</td> <td>600</td> <td>3 E+2 53.3 d</td> </tr> <tr> <td>Mn-54</td> <td>1 E+6</td> <td>10</td> <td>1</td> <td>0.4</td> <td>0.3</td> <td>0.09</td> <td>1</td> <td>10</td> <td>10</td> <td>2 312.2 d</td> </tr> <tr> <td>Fe-64</td> <td>1 E+6</td> <td>1 E+4</td> <td>100</td> <td>200</td> <td>6</td> <td>1 E+3</td> <td>1 E+4</td> <td>2 E+4</td> <td>1 E+4</td> <td>2.7 a</td> </tr> <tr> <td>Zr-95</td> <td>1 E+6</td> <td>10</td> <td>1</td> <td>0.5</td> <td>0.4</td> <td>0.01</td> <td>2</td> <td>10</td> <td>20</td> <td>0.5 244 d</td> </tr> <tr> <td>Co-60</td> <td>1 E+6</td> <td>10</td> <td>1</td> <td>0.1</td> <td>0.09</td> <td>0.03</td> <td>0.4</td> <td>4</td> <td>3</td> <td>0.6 5.3 a</td> </tr> <tr> <td>Os-190</td> <td>1 E+6</td> <td>10</td> <td>1</td> <td>0.9</td> <td>0.2</td> <td>0.08</td> <td>1</td> <td>9</td> <td>30</td> <td>1 70.8 d</td> </tr> <tr> <td>Ag-110m</td> <td>1 E+6</td> <td>10</td> <td>1</td> <td>0.1</td> <td>0.08</td> <td>7E-3</td> <td>0.5</td> <td>3</td> <td>4</td> <td>0.5 249.9 d</td> </tr> <tr> <td>Sr-90</td> <td>1 E+6</td> <td>10</td> <td>1</td> <td>0.5</td> <td>0.5</td> <td>0.04</td> <td>1</td> <td>5</td> <td>20</td> <td>0.5 60.3 d</td> </tr> <tr> <td>Cs-137</td> <td>1 E+4</td> <td>10</td> <td>1</td> <td>0.5</td> <td>0.4</td> <td>0.06</td> <td>2</td> <td>10</td> <td>10</td> <td>0.6 30.2 a</td> </tr> <tr> <td>Cs-134</td> <td>1 E+4</td> <td>10</td> <td>1</td> <td>0.2</td> <td>0.1</td> <td>0.05</td> <td>0.6</td> <td>6</td> <td>5</td> <td>0.2 2.1 a</td> </tr> <tr> <td>Am-241</td> <td>1 E+4</td> <td>1</td> <td>0.1</td> <td>0.05</td> <td>0.05</td> <td>0.06</td> <td>0.1</td> <td>1</td> <td>3</td> <td>0.3 432.6 a</td> </tr> </tbody> </table>	Nucleus	Exemption limit		Surface contamination	General Clearance of			Specific Clearance of		Half-life	Activity [Bq]	Specific activity [Bq/g]	Solid substances, liquids, with the exception of column 6 [Bq/m²]	Building rubble, excavated soil amounts over 1,000 Mg/a [Bq/g]	Buildings for reuse or continued use [Bq/cm²]	Solid substances and liquids for disposal [Bq/m²]	Buildings for demolition [Bq/cm²]	Metal Scrap for Recycling [Bq/g]	H-3	1 E+7	1 E+9	100	1 E+3	60	3	1 E+3	4 E+3	1 E+3	12.3 a	Bk-7	1 E+7	1 E+9	100	30	30	2	80	200	600	3 E+2 53.3 d	Mn-54	1 E+6	10	1	0.4	0.3	0.09	1	10	10	2 312.2 d	Fe-64	1 E+6	1 E+4	100	200	6	1 E+3	1 E+4	2 E+4	1 E+4	2.7 a	Zr-95	1 E+6	10	1	0.5	0.4	0.01	2	10	20	0.5 244 d	Co-60	1 E+6	10	1	0.1	0.09	0.03	0.4	4	3	0.6 5.3 a	Os-190	1 E+6	10	1	0.9	0.2	0.08	1	9	30	1 70.8 d	Ag-110m	1 E+6	10	1	0.1	0.08	7E-3	0.5	3	4	0.5 249.9 d	Sr-90	1 E+6	10	1	0.5	0.5	0.04	1	5	20	0.5 60.3 d	Cs-137	1 E+4	10	1	0.5	0.4	0.06	2	10	10	0.6 30.2 a	Cs-134	1 E+4	10	1	0.2	0.1	0.05	0.6	6	5	0.2 2.1 a	Am-241	1 E+4	1	0.1	0.05	0.05	0.06	0.1	1	3	0.3 432.6 a	<p><b>Decommissioning and Clearance</b></p> <p>Dr. Jörg Feinhals, DMT GmbH &amp; Co. KG FS Secretary of Working Group Disposal</p>  <p><b>1 Definitions</b></p>  <p><b>2 Dose Concept and Derived Values</b></p> <p>First approach: Use of exemption values (before 1989) some countries used exemption levels instead of clearance levels Germany: <math>10^{-4}</math> *exemption level per gram <math>\Rightarrow</math> each 10 kg has less than exemption level but 10 kg is much to low for use as average parameter</p> <p>Second approach: Determination of a clearance value by simple deterministic model (1989-2001) Germany: 0.1 Bq/g for clearance of scrap metal 1.0 Bq/g for clearance of scrap metal via foundry but irrespective of kind of nuclide</p> <p>Third approach: nuclide specific determination of clearance values for different pathways (since 2001)</p> <p><b>4 Why Supervision for Clearance?</b></p> <p>According de minimis concept an activity below clearance levels is of no regulatory concern. But ¼ of the German RPO is dealing with clearance!</p> <p>during operation</p> <p>discharge of aerosols: <math>10^7</math> Bq/y</p> <p>clearance: <math>100 \text{ Mg}/\text{y} \cdot 0.1 \text{ Bq/g} = 10^7 \text{ Bq}/\text{y}</math></p>
Nucleus		Exemption limit			Surface contamination	General Clearance of			Specific Clearance of		Half-life																																																																																																																																												
	Activity [Bq]	Specific activity [Bq/g]	Solid substances, liquids, with the exception of column 6 [Bq/m²]	Building rubble, excavated soil amounts over 1,000 Mg/a [Bq/g]		Buildings for reuse or continued use [Bq/cm²]	Solid substances and liquids for disposal [Bq/m²]	Buildings for demolition [Bq/cm²]	Metal Scrap for Recycling [Bq/g]																																																																																																																																														
H-3	1 E+7	1 E+9	100	1 E+3	60	3	1 E+3	4 E+3	1 E+3	12.3 a																																																																																																																																													
Bk-7	1 E+7	1 E+9	100	30	30	2	80	200	600	3 E+2 53.3 d																																																																																																																																													
Mn-54	1 E+6	10	1	0.4	0.3	0.09	1	10	10	2 312.2 d																																																																																																																																													
Fe-64	1 E+6	1 E+4	100	200	6	1 E+3	1 E+4	2 E+4	1 E+4	2.7 a																																																																																																																																													
Zr-95	1 E+6	10	1	0.5	0.4	0.01	2	10	20	0.5 244 d																																																																																																																																													
Co-60	1 E+6	10	1	0.1	0.09	0.03	0.4	4	3	0.6 5.3 a																																																																																																																																													
Os-190	1 E+6	10	1	0.9	0.2	0.08	1	9	30	1 70.8 d																																																																																																																																													
Ag-110m	1 E+6	10	1	0.1	0.08	7E-3	0.5	3	4	0.5 249.9 d																																																																																																																																													
Sr-90	1 E+6	10	1	0.5	0.5	0.04	1	5	20	0.5 60.3 d																																																																																																																																													
Cs-137	1 E+4	10	1	0.5	0.4	0.06	2	10	10	0.6 30.2 a																																																																																																																																													
Cs-134	1 E+4	10	1	0.2	0.1	0.05	0.6	6	5	0.2 2.1 a																																																																																																																																													
Am-241	1 E+4	1	0.1	0.05	0.05	0.06	0.1	1	3	0.3 432.6 a																																																																																																																																													



**4 Why Supervision for Clearance?**

Fachverband für Strahlenschutz e.V.

According de minimis concept an activity below clearance levels is of no regulatory concern. But ¼ of the German RPO is dealing with clearance!

during decommissioning

discharge of aerosols:  $10^7 \text{ Bq}/\text{y}$

clearance: some 1000 Mg/y \* 0,1 Bq/g >  $10^8 \text{ Bq}/\text{y}$

During decommissioning more activity leaves the plant by clearance than through the stack

Earth. Insight. Values. DMT

**4 Why Supervision for Clearance?**

Fachverband für Strahlenschutz e.V.

According de minimis concept an activity below clearance levels is of no regulatory concern. But ¼ of the German RPO is dealing with clearance!

during decommissioning

discharge of aerosols:  $10^7 \text{ Bq}/\text{y}$

clearance: some 1000 Mg/y \* 0,1 Bq/g >  $10^8 \text{ Bq}/\text{y}$

But the consequence was not to reduce the supervision for the discharge but to increase it for clearance.

Earth. Insight. Values. DMT

**5 IAEA Regulations RS-G-1.7 Criteria for Clearance and Exemption**

Fachverband für Strahlenschutz e.V.

Dose limit (1mSv in a year)

Region for specific clearance of materials, if restrictions fail

some 10  $\mu\text{Sv}$  in a year

Region of specific clearance of materials

10  $\mu\text{Sv}$  in a year

Region of general clearance of materials

Earth. Insight. Values. DMT

**5 IAEA Regulations**

Fachverband für Strahlenschutz e.V.

license required

1000 $\mu\text{Sv}$ 300 $\mu\text{Sv}$	worst case scenario	1 mSv	failure of restriction
100 $\mu\text{Sv}$	some ten $\mu\text{Sv}$ <b>Materials</b> de minimis concept EC-recommendations optimization 1 manSv	graded approach	Sites optimization by defining dose constraints <b>WS-G-5.1</b>
10 $\mu\text{Sv}$	<b>RS-G-1.7</b> no optimization	materials resulting from release of sites	no optimization

movable certainty of reuse fixed

Earth. Insight. Values. DMT

**5 IAEA Regulations**

Fachverband für Strahlenschutz e.V.

Revision RS-G-1.7 and WS-G-5.1  
Results of a Consultancy Meeting Oct. 2014

- check the possibility of a common dose concept for release/clearance of sites and materials
- release of a site today should not lead to a legacy in future
- concept of specific exemption/clearance should be described in more detail and their application as well
- exemption values for moderate amounts are not valid for clearance for moderate amounts. It should be discussed, if these values should be upper limits for specific exemption
- ...

Earth. Insight. Values. DMT

**5 IAEA Regulations**

Fachverband für Strahlenschutz e.V.

Revision RS-G-1.7 and WS-G-5.1  
Results of a Consultancy Meeting Oct. 2014

FS-Workshop on RP Culture and Waste Management Common Dose Concept for Clearance and Release

- IAEA recommends a dose concept for clearance of materials  $10 \mu\text{Sv}/\text{y}$  and for release of sites (buildings plus areas) up to  $300 \mu\text{Sv}/\text{y}$
- Overlap in case of release of building debris or excavated material => Inconsistencies
- A common dose concept would be an ideal solution to repair the dose system, but includes the risk of flexibility, if solutions are necessary for sites with higher contamination
- Different dose concepts are also existent in case of NORM and release of effluents. A detailed definition for the application of all these dose concepts and their overlaps in one guide would be very helpful and increase the acceptance of the recommended dose concepts.

Earth. Insight. Values. DMT

**6 Importance of Clearance for Decommissioning**

Fachverband für Strahlenschutz e.V.

A simple estimation:  
NPP approx.  $100.000 \text{ m}^3$   
actual efficiency for clearance: 97%

If clearance values are modified, clearance efficiency will decrease!  
Assumption: clearance efficiency will drop down from 97% to 88%

$\Rightarrow 100\%-97\% = 3\% \text{ or } 3.000 \text{ m}^3$  radioactive waste  
 $100\%-88\% = 12\% \text{ or } 12.000 \text{ m}^3$  radioactive waste  
 $9.000 \text{ m}^3$  more radioactive waste = 900 Mill. SFr more cost per plant or 4.5 Bill. SFr for 5 plants

$\Rightarrow$  for Germany:  $20 \text{ NPP} * 9.000 \text{ m}^3 = 180.000 \text{ m}^3$  more radioactive waste  
Konrad offers not enough space for decommissioning of NPPs

Earth. Insight. Values. DMT

**6 Importance of Clearance for Decommissioning**

Fachverband für Strahlenschutz e.V.

license registration	activity	material is => radioactive
	no clearance	spec. activity - Table B
exemption from authorisation for moderate amounts, exemption from notification in single case	specific clearance (within single case) specific reuse specific reutilization specific disposal	without permit => radioactive with permit => exempted
exemption	general clearance (without any restrictions)	spec. activity - Table A => not radioactive

Earth. Insight. Values. DMT



<h3>6 Importance of Clearance for Decommissioning</h3> <p><b>Spec. Activity - Table B:</b></p> <ul style="list-style-type: none"> <li>no clearance: material is =&gt; radioactive</li> <li>exemption from authorisation for moderate amounts, exemption from notification in single case</li> <li>specific clearance (within single case)</li> <li>specific reuse</li> <li>specific reutilization</li> <li>specific disposal</li> </ul> <p><b>Spec. Activity - Table A:</b></p> <ul style="list-style-type: none"> <li>activity: no clearance, material is =&gt; radioactive</li> <li>without permit =&gt; radioactive</li> <li>with permit =&gt; exempted</li> <li>exemption</li> <li>general clearance (without any restrictions) =&gt; not radioactive</li> </ul>	<h3>6 Importance of Clearance for Decommissioning</h3> <p><b>Spec. Activity - Table A:</b></p> <ul style="list-style-type: none"> <li>activity: no clearance, material is =&gt; radioactive?</li> <li>exemption</li> <li>general clearance (without any restrictions) =&gt; not radioactive</li> </ul>																																																																																									
<h3>6 Importance of Clearance for Decommissioning</h3> <p><b>Actual</b> (Green Boxes) <b>RS G-1.7</b> (Red Boxes)</p> <p>14.143.9 Mg → General Clearance (52.5%) → 11.268 Mg (~55%)</p> <p>6.444.3 Mg → Melting (45%) → Radioactive Waste (16.827 Mg + 446%)</p> <p>4.427.1 Mg → Clearance for Disposal (100%) → Radioactive Waste (16.827 Mg + 446%)</p> <p><b>Earth. Insight. Values.</b> + 3080 Mg Radioactive Waste <b>DMT</b></p>	<h3>7 Planned Regulations for Switzerland</h3> <table border="1"> <thead> <tr> <th rowspan="2"></th> <th colspan="2">Bq/g</th> <th colspan="2">Bq/cm<sup>3</sup></th> </tr> <tr> <th>LE</th> <th>LL</th> <th>CS alt</th> <th>CS neu</th> </tr> </thead> <tbody> <tr> <td>Be-7</td> <td>400</td> <td><b>10</b></td> <td>1000</td> <td><b>100</b></td> </tr> <tr> <td>C-14</td> <td>20</td> <td><b>1</b></td> <td>-</td> <td>-</td> </tr> <tr> <td>Na-22</td> <td>3</td> <td><b>0,1</b></td> <td>-</td> <td>-</td> </tr> <tr> <td>Al-26</td> <td>3</td> <td><b>0,1</b></td> <td>-</td> <td>-</td> </tr> <tr> <td>Si-32</td> <td>-</td> <td><b>100</b></td> <td>3</td> <td>10</td> </tr> <tr> <td>Cl-36</td> <td>10</td> <td><b>1</b></td> <td>-</td> <td>-</td> </tr> <tr> <td>Ca-41</td> <td>30</td> <td>100</td> <td>-</td> <td>-</td> </tr> <tr> <td>Ti-44</td> <td>2</td> <td><b>0,1</b></td> <td>-</td> <td>-</td> </tr> <tr> <td>Mn-54</td> <td>10</td> <td><b>0,1</b></td> <td>-</td> <td>-</td> </tr> <tr> <td>Fe-55</td> <td>30</td> <td>1000</td> <td>300</td> <td>1000</td> </tr> <tr> <td>Co-57</td> <td>50</td> <td><b>1</b></td> <td>-</td> <td>-</td> </tr> <tr> <td>Co-60</td> <td>1</td> <td><b>0,1</b></td> <td>-</td> <td>-</td> </tr> <tr> <td>Zn-65</td> <td>3</td> <td><b>0,1</b></td> <td>30</td> <td>100</td> </tr> <tr> <td>Cs-137</td> <td>0,8</td> <td><b>0,1</b></td> <td>-</td> <td>-</td> </tr> <tr> <td>Ba-133</td> <td>10</td> <td><b>0,1</b></td> <td>30</td> <td>100</td> </tr> <tr> <td>Eu-152</td> <td>7</td> <td><b>0,1</b></td> <td>-</td> <td>-</td> </tr> </tbody> </table> <p><b>Earth. Insight. Values.</b> <b>DMT</b></p>		Bq/g		Bq/cm <sup>3</sup>		LE	LL	CS alt	CS neu	Be-7	400	<b>10</b>	1000	<b>100</b>	C-14	20	<b>1</b>	-	-	Na-22	3	<b>0,1</b>	-	-	Al-26	3	<b>0,1</b>	-	-	Si-32	-	<b>100</b>	3	10	Cl-36	10	<b>1</b>	-	-	Ca-41	30	100	-	-	Ti-44	2	<b>0,1</b>	-	-	Mn-54	10	<b>0,1</b>	-	-	Fe-55	30	1000	300	1000	Co-57	50	<b>1</b>	-	-	Co-60	1	<b>0,1</b>	-	-	Zn-65	3	<b>0,1</b>	30	100	Cs-137	0,8	<b>0,1</b>	-	-	Ba-133	10	<b>0,1</b>	30	100	Eu-152	7	<b>0,1</b>	-	-
	Bq/g		Bq/cm <sup>3</sup>																																																																																							
	LE	LL	CS alt	CS neu																																																																																						
Be-7	400	<b>10</b>	1000	<b>100</b>																																																																																						
C-14	20	<b>1</b>	-	-																																																																																						
Na-22	3	<b>0,1</b>	-	-																																																																																						
Al-26	3	<b>0,1</b>	-	-																																																																																						
Si-32	-	<b>100</b>	3	10																																																																																						
Cl-36	10	<b>1</b>	-	-																																																																																						
Ca-41	30	100	-	-																																																																																						
Ti-44	2	<b>0,1</b>	-	-																																																																																						
Mn-54	10	<b>0,1</b>	-	-																																																																																						
Fe-55	30	1000	300	1000																																																																																						
Co-57	50	<b>1</b>	-	-																																																																																						
Co-60	1	<b>0,1</b>	-	-																																																																																						
Zn-65	3	<b>0,1</b>	30	100																																																																																						
Cs-137	0,8	<b>0,1</b>	-	-																																																																																						
Ba-133	10	<b>0,1</b>	30	100																																																																																						
Eu-152	7	<b>0,1</b>	-	-																																																																																						
<h3>7 Planned Regulations for Switzerland</h3> <p><b>Earth. Insight. Values.</b> <b>DMT</b></p>	<h3>8 Chances to Reduce the Strong Dependence from Modifications of Clearance Regulations</h3> <h4>a) Decay Storage</h4> <p>Art. 130 Decay storage</p> <p>A decay storage of waste with nuclides with a half life &gt; 100 days with the aim of clearance is limited to a duration of 30 years.</p> <p>=&gt; Reduction of amount of radioactive waste by decay storage</p> <p><b>Earth. Insight. Values.</b> <b>DMT</b></p>																																																																																									
<h3>8 Chances to Reduce the Strong Dependence from Modifications of Clearance Regulations</h3> <h4>b) Removal</h4> <p>Annex IV RPO: Radionuclides with contribution &lt; 10% to radiation exposure can be neglected</p> <p>In this case Fe-55 can be neglected</p> <p>Describe clear, what is never contaminated/activated to reduce the scope for clearance regulations</p> <p><b>Earth. Insight. Values.</b> <b>DMT</b></p>	<h3>8 Chances to Reduce the Strong Dependence from Modifications of Clearance Regulations</h3> <h4>b) Removal</h4> <p><b>Plant Greifswald site 1.800.000 Mg</b></p> <p><b>Category I</b>: Not contaminated Ca. 1.235.000 Mg</p> <p><b>Category II and III</b>: Potentially contaminated Ca. 565.000 Mg</p> <p>Plant components TH 1 – 6, IH 6 Ca. 50.000 Mg</p> <p>Building structures Ca. 1.185.000 Mg</p> <p>Concrete Ca. 26.000 Mg</p> <p>Plant components Ca. 68.000 Mg</p> <p>Remaining building structures Ca. 471.000 Mg</p> <p><b>Removal 2/3</b>      <b>Clearance 1/3</b></p> <p><b>Earth. Insight. Values.</b> <b>DMT</b></p>																																																																																									



## 8 Chances to Reduce the Strong Dependence from Modifications of Clearance Regulations

### c) Recycling

Art. 120 Reuse/Reutilisation of Solid Materials

Use of up to ten times higher clearance values are possible

- ⇒ Scrap is not a radioactive waste, but a raw material only with a slight radioactive contamination!
- Transboundary trade should not be blocked by national regulations.



DMT

## 9 Conclusions



DMT



Earth. Insight. Values.



## 9 Conclusions

The planned clearance regulations for Switzerland are a good basis for future decommissioning projects, but more detailed requirements are necessary for their application especially for

- the clearance of areas accord. Art. 93
- the clearance of scrap in melting facilities without any license
- the clearance of waste for a landfill
- the clearance of waste for incineration

A full revision of the guideline B04 concerning these issues would be very helpful.

Earth. Insight. Values.

DMT



## Decommissioning and its effects on environment



### Decommissioning and its effects on environment

B. Clavel, G. Gontier


Radiation Protection Workshop / Federal Commission on radiation protection / BERN 08/04/2016

## PLAN


1. CONTEXT
2. REGULATORY FRAMEWORK
3. DISCHARGES MONITORING
4. ENVIRONMENTAL MONITORING
5. CONCLUSIONS
6. PHOTOS

Radiation Protection Workshop / BERN 08/04/2016 | 2

### 1 / EDF nuclear power plants under decommissioning in France



### 2 / FRENCH REGULATORY FRAMEWORK



Radiation Protection Workshop / BERN 08/04/2016 | 4



### DISCHARGES MONITORING

edf

| 5

### 3 / PERMITS OF DISCHARGES

NPP	Decision n°	Recent permits		3H (TBq/yr)	14C (GBq/yr)	Other beta or gamma emitters (GBq/yr)	Alpha emitters (MBq/yr)
		Discharge permits	Step				
GAZEOUS radioactive discharges	Décision n°2014-DC-0442	Step 1	0.1	1,5	0,4	0,15	
		Step 2	3	70	2,2	0,2	0,15
		Step 3	0,1	6	0,2		0,15
Chooz A	Décision n°2009-DC-0165	Step 1	0,1	10	0,01		
		Step 2	0,015				
		Step 3	0,015	[100 for vessel]	[0,02 for caskmate and HK]	-	-
Creys-Malville	Arrêté du 03/08/2007	For 10 years	100	-	0,1	-	-
		After 10 years	0,0025	3,15	0,1	-	-
		Out of reactor	4	30	0,1	0,05	
Chinon A	Décision n°2015-DC-0527	Out of reactor	0,7	10	0,02	-	-
		Step 1	0,0002		0,01	-	-
		Step 2	5	120	40	-	-
Brennilis	Décision n°2011-DC-0239	Step 3	0,02	0,65	10	-	-
		Step 1	0,1	[80 water pool]	2	-	-
		Step 2	0,003	-	0,75	-	-
GAZEOUS radioactive discharges	Décision n°2014-DC-0442	Step 3	0,0003	-	30 [8 yrs]	-	-
		Two steps	1	-	5	-	-
			0,00093	0,031	0,86	-	-

Adapted to our needs and to radiological inventories

Radiation Protection Workshop / BERN 08/04/2016 | 6

### 3 / MONITORING RELEASE STRATEGY

#### → OBJECTIVES :

- Ensure compliance with discharge permits thus the associated environmental impact
- Discharge monitoring must be representative

#### → REGULATION :

- Art. 3.2.8 de la « décision environnement » (décision ASN of the 16 July 2013)

=> Criteria to be considered :

- Radiotoxicity : Only RN that represent more than 1 % of the total effective dose of the estimated discharge are considered
- Detection Frequency : Case by case Study
- Metrological constraints : Potential questions ...
  - Possibility of outsourcing analyses
  - Feasibility of determination by calculation
  - Requirement to develop a specific analytical protocol

=> Notion of « Reference radionuclides » : RN are accounted for at the decision threshold

edf

Radiation Protection Workshop / BERN 08/04/2016 | 7

### 3 / SPECIFIC CASE : Chlorine 36 (1/2)

\* Only gaseous RN of its category ( PF / PA ) => Represent an important part of the discharge (not filtered by THE)

\* Analysis Standards of the 36Cl in discharges and waste by liquid scintillation (Norme NF M60-332)

No industrial sampler to capture 36Cl in gaseous discharges

International practices ? → cern

Bibliographical summary

→ Capturing methods for gaseous 36Cl

Manufacturing of a sampler prototype

Trapping and catalytic conversion efficiency, stability of the trapping solution, influence of ageing of the catalyst →


=> Results expected in the second half of 2016

edf

Radiation Protection Workshop / BERN 08/04/2016 | 8



### 3 / RN analysed in GASEOUS discharges




### 3 / Declared GAS emissions


- **Compliance with discharge permits**  
(Correct sizing of the limits)
  - **Alpha : BUG and SLA**  
Often counting at the decision threshold
  - **3H :** Distinction HTO / other forms  
Systematic counting at the decision threshold  
(BUG1 et CHIA)
  - **14C :** 0.2 to 0.5 GBq/ site in 2014  
Systematic counting at the decision threshold  
(BNS et CHIA)
  - **Pf/PA :** Often counting at the decision threshold on all sites  
Declared activities vary according to the "reference spectra" and ventilation flow-rate

Country	Number of sites
CHF	~100
CHN	~80
CHD	~60
CHS	~40
CHL	~30
CHA	~20
CHB	~10

⇒ Discharges globally low, often based on counting radionuclides at the decision thresholds




### 3 / RN analysed in LIQUID discharges



### 3 / Declared LIQUID emissions

- Compliance with discharge permits  
(Correct sizing of the limits)
  - Brennells / St-Laurent A -> No liquid discharges
  - Chooz A  
Chinon A ] Liquid discharges  $\geq$  Infiltrated water  
Bugey 1 ]  
Creys-Malville -> 6 to 8 releases/year at the most (300 m<sup>3</sup>-tank)
  - <sup>3</sup>H : Low annual releases (MBq/year -> GBq/year)
  - **14C :**
    - No liquid discharges (CRM, BUG1, CHIA)
    - Frequent counting at the the decision threshold (CHOA / 0.2 GBq/year)
  - **PF/PA :**
    - Regulatory counting at the decision threshold
    - MBq/year > 0.2 GBq/year (due to different « reference spectra »)

→ Discharges globally low, often based on counting radionuclides at the decision thresholds



## 4 / RADIOLOGICAL MONITORING OF THE ENVIRONMENT AROUND NUCLEAR SITES

- 2 types of observations are necessary and complementary throughout the reactors' life cycle, including decommissioning :

> The regulatory program of radiological monitoring of the environment is prescribed by the French Nuclear Authority (ASN). It aims :

  - To verify the compliance with limits fixed in the decrees => **control**
  - To verify the safe functioning of the installations and assess the potential influence of releases into the environment => **environmental monitoring**

The regulatory programs strictly applied by EDF or its partners.

> This program is completed, under EDF's initiative, by radioecological studies which need more sensitive observation devices to :

  - Understand the transfer mechanisms of artificial radionuclides in the environment
  - Evaluate to what extent the operating or the decommissioning nuclear facilities contribute to the input of artificial radionuclides in the environment  
=> **long term monitoring**


*These studies are carried out by external specialized laboratories, certified by French agencies which follow the French standard for carrying out planning*

- 30 000 samples  
- 62 000 analyses / year

- 600 samples  
- 800 analyses / year

**=> long term monitoring**  
These studies are carried out by external specialized laboratories, certified by French agencies which follow the French standards for sampling and analysis.

**=> long term monitoring**  
These studies are carried out by external specialized laboratories, certified by French agencies, which follow the French standards for sampling and analysis.



## 4 / SPECIAL TRITIUM MONITORING IN THE TERRESTRIAL ENVIRONMENT AT CREYS-MALVILLE – AUTUMN 2012


- TRITIUM RELEASES LINKED TO THE TREATMENT OF A SPECIFIC COMPONENT (UPI2)
    - > UPI : Integrated Unit of Purification
    - > Carbonation operation  
Carbonation is an operation aiming to chemically neutralize the residual sodium by circulation of a gas mixture ( $\text{CO}_2$  + water vapor plus nitrogen). This led to the release of tritium gas, mainly as HT.
    - > 1<sup>st</sup> operation (treatment of UPI1) in 2011: Release of ~ 10 TBq
      - ➡ *EDF decided to reinforce the radiological monitoring to characterize the potential influence of the release on the environment for the*



Handling of the UPI2

## 4 / SPECIAL TRITIUM MONITORING IN THE TERRESTRIAL ENVIRONMENT AT CREYS-MALVILLE – AUTUMN 2012


- TRITIUM RELEASES LINKED TO THE TREATMENT OF A SPECIFIC COMPONENT



Radiation Protection Workshop / BERN 08/04/2016 | 17

## 4 / SPECIAL TRITIUM MONITORING IN THE TERRESTRIAL ENVIRONMENT AT CREYS-MALVILLE – AUTUMN 2012


- RESULTS : ACTIVITY IN AIR UNDER POTENTIAL INFLUENCE OF THE RELEASES (QUINCIÉU FARM)




Radiation Protection Workshop / BERN 08/04/2016 | 19

## 4 / SPECIAL TRITIUM MONITORING IN THE TERRESTRIAL ENVIRONMENT AT CREYS-MALVILLE – AUTUMN 2012

- SAMPLING AND ANALYSES STRATEGY



Radiation Protection Workshop / BERN 08/04/2016 | 18



## 5 / CONCLUSION

### Main characteristics of the monitoring and environmental impact :

- Correct sizing of the current discharge permits despite varied and complex encountered situations (degassing, lixiviation, evaporation ...)
- Very complete and low level monitoring which can include development of adapted analytical protocols (36Cl) or specific environmental studies
- Discharges globally low often based on counting decision thresholds
- Absence of marking or very weak and transitory marking of the environment



Radiation Protection Workshop / BERN 08/04/2016 | 22



Radiation Protection Workshop / BERN 08/04/2016 | 26



Radiation Protection Workshop / BERN 08/04/2016 | 24



Radiation Protection Workshop / BERN 08/04/2016 | 27



# Decommissioning and its effects on environment

Benoit CLAVEL et Gilles GONTIER

EDF-DPNT-DIPDE  
154 avenue Thiers – 69458 LYON cedex 06  
Benoit.clavel@edf.fr

EDF's French nuclear fleet undergoing decommissioning is based on nine shutdown reactors headquartered in six geographical sites. These reactors which operated between 1964 and 1998 fall into four categories:

- - « Natural uranium graphite gas » (Bugey 1, Saint-Laurent A1 et A2 et Chinon A1, A2 et A3) ;
- - « Fast breeder » (Creys-Malville) ;
- - « Heavy water reactor » (Brennilis) ;
- - « Pressurised water reactor » (Chooz A, first PWR operating in France)

The strategy adopted for nuclear decommissioning is to eliminate progressively the radiological risk starting with secondary circuit and ending on the reactor. The space freed up allows reorganising buildings to accommodate support functions necessary for reactor dismantling (water treatment system, equipment for cutting and conditioning waste...).

When the radiological risk is removed, the next step is to finalise actions taken to remediate contaminated soil, demolish conventional buildings, backfill excavations and organise space framework in compliance with the future use of the site.

To date, the nuclear power plants of Creys-Malville, Chooz A and Bugey 1 have discharge authorisations for complete decommissioning. It's not the case for Brennilis, Chinon A3 and Saint-Laurent A1 et A2 which have discharge permits only for circuits located on the outskirts of the reactor. No dismantling activity is carried out at Chinon A1 and A2.

To execute a dismantling project, it's necessary to investigate environmental issues beforehand. Preliminary studies consist of estimating potential radiological and chemical discharges from dismantling operations to size permits and associated monitoring.

A health and environmental assessment is then undertaken on the basis of the permits requests asked by the nuclear operator.







The purpose of the presentation is to provide inputs about:

- permits of discharges ;
- discharges monitoring requirements ;
- dismantling discharges already done ;
- environmental monitoring strategy.

EDF has consolidated the acquired knowledge on discharges in particular during day-to-day operation of shutdown NPP as well as during dismantling operations. Discharges need to be taken into account at a level that is proportionate to the environmental issues at stake.



## Decommissioning of KKM in a radiological perspective

 <p><b>Decommissioning of KKM from a radiological perspective</b></p> <p>KSR   LIEBEFELD, 8 APRIL 2016</p> <p><b>BKW</b></p>	<p>DECOMMISSIONING KKM – KSR   BKW   APRIL 8<sup>th</sup>, 2016 2</p> <p><b>Step by step towards the decommissioning order</b></p> <p><b>Hermann Bühliger, Head of Production and member of BKW corporate management, and member of the decommissioning project team Peter Schmid, Vice-President of the Swiss Federal Office of Energy (SFOE) in Biel.</b></p> <p><b>Important</b></p> <ul style="list-style-type: none"> <li>– October 30<sup>th</sup>, 2013: BKW takes the corporate decision to decommission the nuclear power plant (NPP) Mühleberg</li> <li>– December 18<sup>th</sup>, 2015: BKW submits the decommissioning project to the Swiss Federal Office of Energy</li> <li>– December 20<sup>th</sup>, 2019: BKW ceases the operation of NPP Mühleberg</li> </ul> <p><b>Nuclear decommissioning is technically proven</b></p> <p><b>Pioneering project in Switzerland for politics, administration, the community and BKW</b></p> <p>We are pioneers in Switzerland and build upon international decommissioning and dismantling experience</p>
<p>DECOMMISSIONING KKM – KSR   BKW   APRIL 8<sup>th</sup>, 2016 3</p> <p><b>An overview of the decommissioning project</b></p> <p>Decommissioning Project (Main report), Accident analysis &amp; emergency preparedness measures (Part 1), Environmental impact report (Part 2), Security measures (Part 3), Application letter</p> <p>Authorities check the compliance with the law and the state of the art</p>	<p>DECOMMISSIONING KKM – KSR   BKW   APRIL 8<sup>th</sup>, 2016 4</p> <p><b>How we decommission KKM</b></p> 
<p>DECOMMISSIONING KKM – KSR   BKW   APRIL 8<sup>th</sup>, 2016 5</p> <p><b>Preparation of dismantling 2019-2020</b></p>  <p>A. Unloading the reactor pressure vessel (transfer of spent fuel to the spent fuel pool) B. Installation of the safety grade spent fuel pool cooling system C. Removal of mobile equipment in the reactor building at ~29m D. Removal of components in the turbine hall</p>	<p>DECOMMISSIONING KKM – KSR   BKW   APRIL 8<sup>th</sup>, 2016 6</p> <p><b>Removal of spent fuel - Nuclear dismantling 2021-2024</b></p>  <p>E. Installation of material treatment equipment F. Disassembly of heating systems and initiation of decontamination of facilities and buildings G. Disassembly of reactor internals</p>
<p>DECOMMISSIONING KKM – KSR   BKW   APRIL 8<sup>th</sup>, 2016 7</p> <p><b>Nuclear dismantling 2025-2031</b></p>  <p>A. Disassembly of spent fuel pool cooling systems B. Disassembly of post irradiation handling system C. Disassembly of reactor pressure vessel (RPV) D. Removal of personnel and material arrester E. Disassembly of drywell components F. Disassembly of steam pipes and feed water pipes G. Disassembly of upper part of the biological shield H. Disassembly of drywell vessel liner I. Disassembly of steam dryer and moisture separator storage pool liner and RPV cavity J. Disassembly of all remaining systems, e.g. reactor water clean up system K. Decontamination of facilities and buildings L. Operation of material treatment equipment M. Disassembly of systems in the SUSAN building</p>	<p>DECOMMISSIONING KKM – KSR   BKW   APRIL 8<sup>th</sup>, 2016 8</p> <p><b>Final state at completion of nuclear dismantling 2031</b></p>  <p>1. SUSAN building 3. Reactor building (Secondary containment) 19. Steam dryer and moisture separator storage pool 21. Turbine hall 17. Spent fuel pool</p>
<p>DECOMMISSIONING KKM – KSR   BKW   APRIL 8<sup>th</sup>, 2016 9</p> <p><b>Discharges to air and water remain low</b></p> 	<p>DECOMMISSIONING KKM – KSR   BKW   APRIL 8<sup>th</sup>, 2016 10</p> <p><b>With the application letter we submit nine requests</b></p>  <p>1. Decommissioning order for direct dismantling according to the submitted decommissioning project 2. Definition of the scope of the decommissioning activities according to the submitted decommissioning project 3. Dividing of the decommissioning activities into three decommissioning phases 4. Release of BKW from the liability to guarantee nuclear safety and security and termination of supervision by the decommissioning authorities after completion of the radiological clearance measurements 5. Implementation of "Preparatory Measures" after final cease of operation 6. Definition of limits for radioactive discharges 7. Definition of the organisational structure according to the submitted decommissioning project 8. issuance of the required permits by ENSI for the decommissioning phases as well as the activities defined in Art. 47, Nuclear Energy Ordinance 9. Definition of provisions for the withdrawal and return of cooling water from and to the Aare</p>



<p><b>The hazard potential decreases rapidly after the permanent shutdown</b></p>	<p><b>The distribution of iodine tablets will become obsolete at the time of permanent shutdown</b></p>	
<p><b>Where do the dismantled materials end up?</b></p>	<p><b>Challenges from a radiological perspective</b></p> <ol style="list-style-type: none"> <li>1 Decay storage and the radiological protection ordinance (RPO)</li> <li>2 Averaging surface for clearance measurements and the RPO</li> <li>3 International transports to metal treatment facilities</li> </ol> <p>— Details on following pages</p>	
<p><b>① Decay storage and the radiological protection ordinance: Relevant materials to be defined as radioactive materials/substances</b></p> <table border="1"> <tr> <td style="vertical-align: top;"> <b>NEA / RPA</b> Art. 3 / Art. 25 Radioaktive Abfälle: radioaktive Stoffe oder radikalisch kontaminierte Materialien, die nicht weiter verwendet werden  6. Kapitel: Radioaktive Abfälle Art. 119 Begrenzung der Nutzung von radioaktiven Abfällen a. welche nicht nach Artikel 118 festgemessen werden können: befesten und füssigen Stoffen; oder [...]</td> <td style="vertical-align: top;"> <b>RPO (revised)</b> Art. 130 Abfalllagerung [...] Radioaktive Abfälle, deren Aktivität aufgrund des radioaktiven Zerfalls spätestens 30 Jahre nach dem Ende ihrer Verwendung somit abgeklungen ist, müssen nach Artikel 119 festgemessen nach Artikeln 122-125 an die Umwelt abgegeben werden können, sollen bis zum Erreichen dieses Zeitpunktes gelagert werden. Sie sind von den Vorschriften, welche diese Bedingung nicht erfüllen, zu trennen.</td> </tr> </table> <p><b>② Averaging surface for clearance measurements and the radiological protection ordinance: Averaging surface for buildings drive the effort</b></p> <p>- The revised Radiological Protection Ordinance defines in Annex 3 the averaging surface for clearance measurements: – 0.01 m<sup>2</sup> for people, work surfaces and circulation areas – 0.03 m<sup>2</sup> for transports and clearance measurements of materials – 0.1 m<sup>2</sup> for clearance measurements of buildings.  - The clearance measurements of KKM buildings would require approx. one million measurements  - This averaging surface prohibits the use of state-of-the-art measuring methods  - The goal is to set an averaging surface of &gt;1 m<sup>2</sup></p>	<b>NEA / RPA</b> Art. 3 / Art. 25 Radioaktive Abfälle: radioaktive Stoffe oder radikalisch kontaminierte Materialien, die nicht weiter verwendet werden  6. Kapitel: Radioaktive Abfälle Art. 119 Begrenzung der Nutzung von radioaktiven Abfällen a. welche nicht nach Artikel 118 festgemessen werden können: befesten und füssigen Stoffen; oder [...]	<b>RPO (revised)</b> Art. 130 Abfalllagerung [...] Radioaktive Abfälle, deren Aktivität aufgrund des radioaktiven Zerfalls spätestens 30 Jahre nach dem Ende ihrer Verwendung somit abgeklungen ist, müssen nach Artikel 119 festgemessen nach Artikeln 122-125 an die Umwelt abgegeben werden können, sollen bis zum Erreichen dieses Zeitpunktes gelagert werden. Sie sind von den Vorschriften, welche diese Bedingung nicht erfüllen, zu trennen.
<b>NEA / RPA</b> Art. 3 / Art. 25 Radioaktive Abfälle: radioaktive Stoffe oder radikalisch kontaminierte Materialien, die nicht weiter verwendet werden  6. Kapitel: Radioaktive Abfälle Art. 119 Begrenzung der Nutzung von radioaktiven Abfällen a. welche nicht nach Artikel 118 festgemessen werden können: befesten und füssigen Stoffen; oder [...]	<b>RPO (revised)</b> Art. 130 Abfalllagerung [...] Radioaktive Abfälle, deren Aktivität aufgrund des radioaktiven Zerfalls spätestens 30 Jahre nach dem Ende ihrer Verwendung somit abgeklungen ist, müssen nach Artikel 119 festgemessen nach Artikeln 122-125 an die Umwelt abgegeben werden können, sollen bis zum Erreichen dieses Zeitpunktes gelagert werden. Sie sind von den Vorschriften, welche diese Bedingung nicht erfüllen, zu trennen.	
<p><b>All times safe and efficient</b></p> <ul style="list-style-type: none"> <li>- During decommissioning we work with the <b>same safety standards</b> as during power operation</li> <li>- We make <b>good progress</b> with the planning of decommissioning</li> <li>- We are <b>pioneers</b> in Switzerland and build upon international experience: the decommissioning of nuclear power plants is technically proven</li> <li>- We capitalise on the <b>competences of our employees</b> and prepare them already today for the decommissioning</li> <li>- <b>Immediate dismantling</b> is in the best interest of all stakeholders</li> </ul>	<p><b>Questions?</b></p> <p>Further information is available at: <a href="http://www.bkw.ch/stilllegung">www.bkw.ch/stilllegung</a></p>	
<p><b>Processing the resulting radioactive material</b></p> <ul style="list-style-type: none"> <li>- After the final cease of operation we clear the turbine hall and prepare it for <b>material processing activities</b></li> <li>- Decontamination of materials will be performed in <b>additionally closed caissons with filtered exhaust air</b></li> </ul>	<p><b>Installation of decontamination equipment</b></p>	



## Decommissioning of KKM from a radiological perspective

For the Swiss operators, the decommissioning of KKM represents a pilot project with reference character. BKW submitted the decommissioning project on December 18, 2015 to the competent authorities, outlining the direct dismantling of the Mühleberg nuclear power plant. With the removal of fuel elements and the decay of radioactivity, the hazard potential decreases rapidly after the permanent shutdown of the facility. One element for the success of the decommissioning activities is the efficiency of all three disposal channels: free release, decay storage and radioactive waste. Due to the dimension of the project all criteria for handling and treatment of radioactive material with the goal of free release as well as clearance of materials, buildings and soil areas have a significant importance for the project.



NPP Mühleberg - KKW Mühleberg – CN Mühleberg

